entities, such as colleges, universities, and non-profit hospitals, a guarantee of funds by the applicant or licensee may be used if the guarantee and test are as contained in Appendix E to Part 30. A guarantee by the applicant or licensee may not be used in combination with any other financial methods used to satisfy the requirements of this section or in any situation where the applicant or licensee has a parent company holding majority control of the voting stock of the company. Any surety method or insurance used to provide financial assurance for decommissioning must contain the following conditions:

PART 72—LICENSING REQUIREMENTS FOR THE INDEPENDENT STORAGE OF SPENT **NUCLEAR FUEL AND HIGH-LEVEL**

11. The authority citation for Part 72 continues to read as follows:

RADIOACTIVE WASTE

Authority: Secs. 51, 53, 57, 62, 63, 65, 69, 81, 161, 182, 183, 184, 186, 187, 189, 68 Stat. 929, 930, 932, 933, 934, 935, 948, 953, 954, 955, as amended, sec. 234, 83 Stat. 444, as amended (42 USC 2071, 2073, 2077, 2092, 2093, 2095, 2099, 2111, 2201, 2232, 2233, 2234, 2236, 2237, 2238, 2282); sec. 274, Pub. L. 86-373, 73 Stat. 688, as amended (42 USC 2021); sec. 201, as amended, 202, 206, 88 Stat. 1242, as amended, 1244, 1246 (42 USC 5841, 5842, 5846); Pub. L. 95-601, sec. 10, 92 Stat. 2951 (42 USC 5851); sec. 102, Pub. L. 91-190, 83 Stat. 853 (42 USC 4332); Secs. 131, 132, 133, 135, 137, 141, Pub. L. 97-425, 96 Stat. 2229, 2230, 2232, 2241, sec. 148, Pub. L. 100-203, 101 Stat. 1330-235 (42 USC 10151, 10152, 10153, 10155, 10157, 10161, 10168).

Section 72.44(g) also issued under secs. 142(b) and 148(c), (d), Pub. L. 100-203, 101 Stat. 1330-232, 1330-236 (42 USC 10162(b), 10168(c), (d)). Section 72.46 also issued under sec. 189, 68 Stat. 955 (42 USC 2239); sec. 134, Pub. L. 97-425, 96 Stat. 2230 (42 USC 10154). Section 72.96(d) also issued under sec. 145(g), Pub. L. 100-203, 101 Stat. 1330-235 (42 USC 10165(g)). Subpart J also issued under secs. 2(2), 2(15), 2(19), 117(a), 141(h), Pub. L. 97-425, 96 Stat. 2202, 2203, 2204, 2222, 2244 (42 USC 10101, 10137(a), 10161(h)). Subparts K and L are also issued under sec. 133, 98 Stat. 2230 (42 USC 10153) and sec. 218(a), 96 Stat. 2252 (42 USC

12. In § 72.30 the introductory text of paragraph (c)(2) is revised to read as follows:

§72.30 Decommissioning Planning including financing and recordkeeping.

(2) A surety method, insurance, or other guarantee method. These methods guarantee that decommissioning costs

will be paid. A surety method may be in the form of a surety bond, letter of credit, or line of credit. A parent company guarantee of funds for decommissioning costs based on a financial test may be used if the guarantee and test are as contained in Appendix A to Part 30. A parent company guarantee may not be used in combination with other financial methods to satisfy the requirements of this section. For commercial corporations that issue bonds, a guarantee of funds by the applicant or licensee for decommissioning costs based on a financial test may be used if the guarantee and test are as contained in Appendix C to Part 30. For commercial corporations that do not issue bonds, a guarantee of funds by the applicant or licensee for decommissioning costs may be used if the guarantee and test are as contained in Appendix D to Part 30. A guarantee by the applicant or licensee may not be used in combination with any other financial methods used to satisfy the requirements of this section or in any situation where the applicant or licensee has a parent company holding majority control of the voting stock of the company. Any surety method or insurance used to provide financial assurance for decommissioning must contain the following conditions:

Dated at Rockville, Maryland, this 24th day of April, 1997.

For the Nuclear Regulatory Commission. John C. Hoyle,

Secretary of the Commission. [FR Doc. 97-11203 Filed 4-29-97; 8:45 am] BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96-NM-221-AD] RIN 2120-AA64

Airworthiness Directives; Saab Model **SAAB 2000 Series Airplanes**

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking

(NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Saab Model SAAB 2000 series airplanes. This proposal would require replacing the Abex alternating current (AC) electric motor with a new modified

Abex AC electric motor having an improved fan. This proposal is prompted by reports indicating that the integrated hydraulic package (IHP) unit stopped functioning during flight because the fan on the AC electric motor came into contact with the housing of the motor due to inadequate clearance. The actions specified by the proposed AD are intended to prevent loss of IHP function that, if combined with other hydraulic system failures, could result in reduced controllability of the airplane.

DATES: Comments must be received by June 9, 1997.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 96-NM-221-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from SAAB Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping,

This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Ruth Harder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (206) 227-1721; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments

submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 96–NM–221–AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 96-NM-221-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Luftfartsverket (LFV), which is the airworthiness authority for Sweden, recently notified the FAA that an unsafe condition may exist on certain Saab Model SAAB 2000 series airplanes. The LFV advises of reports indicating that the integrated hydraulic package (IHP) unit suddenly stopped functioning during flight because the fan on the alternating current (AC) electric motor came into contact with the housing of the motor due to inadequate clearance. This condition, if not corrected, and if combined with other failures in the hydraulic system, could result in reduced controllability of the airplane.

Explanation of Relevant Service Information

Saab has issued Service Bulletin 2000–29–004, dated September 18, 1995, which describes procedures for replacing the Abex AC electric motor with a new modified Abex AC electric motor having an improved fan. This service bulletin also includes Attachment 1 (Abex NWL Service Bulletin 42103–29–232, dated August 23, 1995) and Attachment 2 (Abex NWL Service Bulletin, 4208901–29–232, dated September 15, 1995). These attachments provide specific procedures for replacing certain Abex AC electric motors.

The LFV classified this service bulletin as mandatory and issued Swedish airworthiness directive SAD 1– 076, dated September 18, 1995, in order to assure the continued airworthiness of these airplanes in Sweden.

FAA's Conclusions

This airplane model is manufactured in Sweden and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LFV has kept the FAA informed of the situation described above. The FAA has examined the findings of the LFV, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require replacing the Abex AC electric motor with a new modified Abex AC electric motor having an improved fan. These actions would be required to be accomplished in accordance with the service bulletin described previously.

Cost Impact

The FAA estimates that 2 Saab Model SAAB 2000 series airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 8 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would be provided by the manufacturer at no cost to operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$960, or \$480 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1)

is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

SAAB Aircraft AB: Docket 96-NM-221-AD.

Applicability: Model SAAB 2000 series airplanes, serial numbers –004 through –029 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of the integrated hydraulic package (IHP) function that, if combined with other hydraulic system failures, could result in reduced controllability of the airplane, accomplish the following:

(a) Within 4 months after the effective date of this AD, replace the Abex alternating current (AC) electric motor with a new

modified Abex AC electric motor having an improved fan, in accordance with Saab Service Bulletin 2000–29–004, dated September 18, 1995, including Attachment 1 (Abex NWL Service Bulletin 42103–29–232, dated August 23, 1995) and Attachment 2 (Abex NWL Service Bulletin 4208901–29–232, dated September 15, 1995).

(b) As of the effective date of this AD, no person shall install an Abex AC electrical motor, part number (P/N) 42103, Model HPS1VC-02; or an Abex AC electrical motor, P/N 4208901, Model HPS1VC-01-01; on any airplane.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM–113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 23, 1997.

Neil D. Schalekamp,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 97–11093 Filed 4–29–97; 8:45 am] BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 97-AEA-020]

Proposed Establishment of Class E Airspace; Sayre, PA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposed rule would establish Class E airspace at Sayre, PA. The development of a new Standard Instrument Approach Procedure (SIAP), Helicopter Point In Space Approach based on the Global Positioning System (GPS), and serving the Robert Parker Hospital Heliport, has made this proposal necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations to the heliport. The area would be depicted on aeronautical charts for pilot reference.

DATES: Comments must be received on or before May 30, 1997.

ADDRESSES: Send comments on the proposed rule in triplicate to: Manager, Operations Branch, AEA–530, Docket no. 97–AEA–020, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy Int'l Airport, Jamaica, NY 11430. The official docket may be examined in the Office of the Assistant Chief Counsel, AEA–7, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, New York 11430.

An informal docket may also be examined during normal business hours in the Operations Branch, AEA–530, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, NY 11430.

FOR FURTHER INFORMATION CONTACT: Mr. Francis T. Jordan, Jr., Airspace Specialist, Operations Branch, AEA—

Specialist, Operations Branch, AEA–530, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, New York 11430; telephone: (718) 553–4521.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 97– AEA-020". The postcard will be date/ time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in the light of comments received. All comments submitted will be available for examination in the Rules Docket both before and after the closing date for comments. A report summarizing each substantive public contact with the FAA

personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Office of the Assistant Chief Counsel, AEA-7, F.A.A. Eastern Region, Federal Building #111, John F. Kennedy International Airport, Jamaica, NY 11430.

Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11–2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to Part 71 of the Federal Aviation Regulations (14 CFR part 71) to establish Class E airspace extending upward from 700 feet above the surface (AGL) at Sayre, PA. A GPS Point In Space Approach has been developed for Robert Parker Hospital Heliport. Additional controlled airspace extending upward from 700 feet above the surface (AGL) is needed to accommodate this approach and for IFR operations to the heliport. The area would be depicted on appropriate aeronautical charts.

Class E airspace designations for airspace extending upward from 700 feet above the surface are published in paragraph 6005 of FAA Order 7400.9D, dated September 4, 1996, and effective September 16, 1996, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that would only affect air traffic procedures and air navigation, it is certified that this proposed rule would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.