

No. 205. They supplied two "Notice of Equipment Compliance" reports. The first one provided compliance information for the material that was used in the vehicle prior to inclusion of the marking and that expired in 1998. TMC also provided a second set of compliance information for the same material, which was used after the marking was placed on the airdam. TMC claims there is virtually no difference between the compliance data; therefore, TMC believes that there is no safety risk.

TMC maintains that, although this failure to mark constitutes a noncompliance with the marking requirements of FMVSS No. 205, it is inconsequential to motor vehicle safety and, therefore, TMC should be exempted from the notification and remedy requirements of the National Traffic and Motor Vehicle Safety Act.

Availability of the Petition and other Documents

The petition and other relevant information are available for public inspection in NHTSA Docket No. NHTSA-2002-12367. You may call the Docket at (202) 366-9324 or you may visit the Docket Management in Room PL-401, 400 Seventh Street, SW., Washington, DC 20590 (10:00 a.m. to 5:00 p.m., Monday through Friday). You may also view the petition and other relevant information on the internet. To do this, do the following:

(1) Go to the Docket Management System (DMS) web page of the Department of Transportation (<http://dms.dot.gov/>).

(2) On that page, click on "Simple Search."

(3) On the next page (<http://dms.dot.gov/searchform.simple.cfm/>), type in the docket number "12367." After typing the docket number, click on "Search."

(4) On the next page, which contains docket summary information for the docket you selected, click on the desired comments. You may download the comments and other materials.

Comments

Interested persons are invited to submit written data, views and arguments on the petition of TMC described above. Comments should refer to the Docket Number and be submitted to: Docket Management, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590. It is requested that two copies be submitted.

All comments received before the close of business on the closing date indicated below will be considered. The application and supporting materials, and all comments received after the

closing date, will also be filed and will be considered to the extent practicable. When the application is granted or denied, the Notice will be published in the **Federal Register** pursuant to the authority indicated below.

Comment closing date: August 7, 2002.

(49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.50 and 49 CFR 501.8)

Issued on: July 2, 2002.

Stephen R. Kratzke,
Associate Administrator for Safety Performance Standards.

[FR Doc. 02-17012 Filed 7-5-02; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

Research and Special Programs Administration

[Docket No. RSPA-2002-11270, Notice No. 02-6]

Safety Advisory: Unauthorized Marking of Compressed Gas Cylinders

AGENCY: Research and Special Programs Administration (RSPA), DOT.

ACTION: Safety advisory notice.

SUMMARY: This is to notify the public that the Department of Transportation is investigating the unauthorized marking of high- and low-pressure compressed gas cylinders, primarily fire extinguishers and self-contained breathing apparatuses, by Tech Fire and Safety, Inc. (Tech Fire). Tech Fire is located at 514 4th Street, Watervliet, NY 12189. In 2000, Research and Special Programs Administration (RSPA) conducted an investigation and evaluation of Tech Fire's DOT specification and exemption cylinder retesting procedures and determined that Tech Fire was not fit to conduct such retests. Consequently, RSPA terminated Tech Fire's approval to test DOT specification and exemption cylinders on October 2, 2001. RSPA subsequently received information that Tech Fire had continued to retest and mark DOT specification cylinders as properly tested in accordance with the Hazardous Materials Regulations (HMR) after its approval to retest had been revoked.

A hydrostatic retest and visual inspection, conducted as prescribed in the HMR, are used to verify the structural integrity of a cylinder. If the hydrostatic retest and visual inspection are not performed in accordance with the HMR, a cylinder with compromised structural integrity may be returned to service when it should be condemned.

Extensive property damage, serious personal injury, or death could result from rupture of a cylinder. Cylinders not retested in accordance with the HMR may not be charged or filled with compressed gas or other hazardous material and offered for transportation in commerce. Only DOT-approved facilities are authorized to perform cylinder hydrostatic retesting.

FOR FURTHER INFORMATION CONTACT:

Chris Michalski, Hazardous Materials Enforcement Specialist, Eastern Region, Office of Hazardous Materials Enforcement, Research and Special Programs Administration, U.S. Department of Transportation, 820 Bear Tavern Road, Suite 306, W. Trenton, NJ 08034. Telephone: (609) 989-2256, Fax: (609) 989-2277.

SUPPLEMENTARY INFORMATION: Through its previous investigations of Tech Fire, RSPA determined that Tech Fire demonstrated a history of non-compliance with the HMR and of improper retesting of cylinders. Based on this non-compliance, RSPA terminated Tech Fire's approval to retest DOT specification and exemption cylinders on October 2, 2001. Subsequently, RSPA was notified that Tech Fire had continued to represent cylinders as being properly retested in accordance with the HMR after its approval to conduct such retests was no longer valid.

The purpose of this safety advisory is to notify the public that Tech Fire is not authorized to retest DOT specification or exemption cylinders. Anyone who has a cylinder serviced by Tech Fire after October 2, 2001, should consider the cylinder unsafe and not fill it with a hazardous material unless the cylinder is first properly retested by a DOT-authorized retest facility.

Cylinders described in this safety advisory that are filled with an atmospheric gas should be vented or otherwise safely discharged. Cylinders that are filled with a material other than an atmospheric gas should not be vented, but instead should be safely discharged. Upon discharge, the cylinders should be taken to a DOT-authorized cylinder retest facility for proper retest to determine compliance with the HMR and to ensure their suitability for continuing service. The inspector can provide a list of authorized retest facilities in your area, or you may obtain the list at the following Web site: <http://hazmat.dot.gov>. Under no circumstances should a cylinder described in this safety advisory be filled, refilled or used for its intended purpose until it is reinspected and

retested by a DOT-authorized retest facility.

Tech Fire's Retester Identification Number (RIN) was B753. The cylinders in question are stamped or labeled with RIN B753 in the following pattern:

B7
M Y
35

M is the month of retest (e.g., 10), and Y is the year of the retest (e.g., 01).

RSPA requests that any person possessing a cylinder described in this safety advisory telephone or provide a facsimile to Inspector Michalski with the following information for each cylinder: (1) The cylinder manufacturer's name, (2) the serial number of the cylinder, (3) the DOT specification or exemption information for the cylinder, and (4) the month and year of the last marked retest by Tech Fire.

Issued in Washington, D.C. on July 2, 2002.

Robert A. McGuire,

Associate Administrator for Hazardous Materials Safety.

[FR Doc. 02-16999 Filed 7-5-02; 8:45 am]

BILLING CODE 4910-60-P

DEPARTMENT OF THE TREASURY

Office of Thrift Supervision

Submission for OMB Review; Comment Request

AGENCY: Office of Thrift Supervision (OTS), Treasury.

ACTION: Notice and request for comment.

SUMMARY: The proposed information collection requirement described below has been submitted to the Office of Management and Budget (OMB) for review, as required by the Paperwork Reduction Act of 1995. OTS is soliciting public comments on the proposal.

DATES: Submit written comments on or before August 7, 2002.

ADDRESSES: Send comments, referring to the collection by title of the proposal or by OMB approval number, to OMB and OTS at these addresses: Joseph F. Lackey, Jr., Office of Information and Regulatory Affairs, Office of Management and Budget, Room 10202, New Executive Office Building, Washington, DC 20503, or e-mail to Joseph_F._Lackey_Jr@omb.eop.gov; and Information Collection Comments, Chief Counsel's Office, Office of Thrift Supervision, 1700 G Street NW., Washington, DC 20552, fax to (202)

906-6518, or e-mail to infocollection.comments@ots.treas.gov. OTS will post comments and the related index on the OTS Internet Site at <http://www.ots.treas.gov>. In addition, interested persons may inspect comments at the Public Reading Room, 1700 G Street NW., by appointment. To make an appointment, call (202) 906-5922, send an e-mail to publicinfo@ots.treas.gov, or send a facsimile transmission to (202) 906-7755.

FOR FURTHER INFORMATION CONTACT: To obtain a copy of the submission to OMB, contact Marilyn K. Burton at marilyn.burton@ots.treas.gov, (202) 906-6467, or facsimile number (202) 906-6518, Regulations and Legislation Division, Chief Counsel's Office, Office of Thrift Supervision, 1700 G Street NW., Washington, DC 20552.

SUPPLEMENTARY INFORMATION: OTS may not conduct or sponsor an information collection, and respondents are not required to respond to an information collection, unless the information collection displays a currently valid OMB control number. As part of the approval process, we invite comments on the following information collection.

Title of Proposal: Annual Thrift Satisfaction Survey.

OMB Number: 1550-0087.

Form Number:

Description: This survey will be sent to federal savings associations on an annual basis to obtain information about their satisfaction with OTS services.

Type of Review: Renewal.

Affected Public: Savings Associations.

Estimated Number of Respondents: 300.

Estimated Frequency of Response: Annually.

Estimated Burden Hours per Response: .25 hours.

Estimated Total Burden: 75 hours.

Clearance Officer: Marilyn K. Burton, (202) 906-6467, Office of Thrift Supervision, 1700 G Street NW., Washington, DC 20552.

OMB Reviewer: Joseph F. Lackey, Jr., (202) 395-7316, Office of Management and Budget, Room 10202, New Executive Office Building, Washington, DC 20503.

Dated: June 27, 2002.

Deborah Dakin,

Deputy Chief Counsel, Regulations and Legislation Division.

[FR Doc. 02-16909 Filed 7-5-02; 8:45 am]

BILLING CODE 6720-01-P

DEPARTMENT OF THE TREASURY

Submission for OMB Review; Comment Request

June 28, 2002.

The Department of Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104-13. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 2110, 1425 New York Avenue NW., Washington, DC 20220.

DATES: Written comments should be received on or before August 7, 2002 to be assured of consideration.

Internal Revenue Service (IRS)

OMB Number: 1545-1128.

Form Number: IRS Form 8814.

Type of Review: Extension.

Title: Parents' Election To Report Child's Interest and Dividends.

Description: Form 8814 is used by parents who elect to report the interest and dividend income of their child under age 14 on their own tax return. If this election is made, the child is not required to file a return.

Respondents: Individuals or households.

Estimated Number of Respondents/Recordkeepers: 1,100,000.

Estimated Burden Hours Per Respondent/Recordkeeper:

Recordkeeping—26 min.

Learning about the law or the form—9 min.

Preparing the form—24 min.

Copying, assembling, and sending the form to the IRS—16 min.

Frequency of Response: Annually.

Estimated Total Reporting/Recordkeeping Burden: 1,408,000 hours.

Clearance Officer: Glenn Kirkland (202) 622-3428, Internal Revenue Service, Room 6411-03, 1111 Constitution Avenue, NW., Washington, DC 20224.

OMB Reviewer: Joseph F. Lackey, Jr. (202) 395-7316, Office of Management and Budget, Room 10235, New Executive Office Building, Washington, DC 20503.

Mary A. Able,

Departmental Reports, Management Officer.

[FR Doc. 02-16910 Filed 7-5-02; 8:45 am]

BILLING CODE 4830-01-P