

Subject

(d) Air Transport Association of America (ATA) Code: 5321, Frame; and 1497, Miscellaneous wiring.

Reason

(e) The mandatory continued airworthiness information (MCAI) states:

During a flight a burning odour [sic] could be smelled in the cabin. Its reason was a short circuit in the LH cable channel, which was caused by a damaged wire harness. The wire harness was damaged by the side channel cover's attachment hardware.

The rubbing and chafing of the wiring harnesses in the tunnels underneath the channel cover, against the screws and rivets attaching the channel covers, could lead to a short circuit of the wiring harness and a subsequent fire in the helicopter.

Actions and Compliance

(f) Within 25 hours time-in-service (TIS), unless already done, do the following:

(1) Inspect the wiring harnesses for chafing and wear in the areas shown in Figure 1 of Eurocopter Alert Service Bulletin EC135-53A-017, Revision 1, dated June 22, 2007 (ASB).

(i) If chafing or wear is found on the wiring harness, before further flight, replace the wiring harness with an airworthy wiring harness.

(ii) If no chafing or wear is found, modify the side channel covers by affixing double-sided adhesive tape in the area depicted in Figure 2 of the ASB by following the Accomplishment Instructions, paragraph C, of the ASB.

(2) Modify the attachment of the copilot collective lever cover as depicted in Figure 3 of the ASB by following the Accomplishment Instructions, paragraph D, of the ASB.

(3) Attach chafing protection to the wiring harnesses and replace affected screws as depicted in and in accordance with Figure 4 of the ASB and by following the Accomplishment Instructions, paragraphs E and F, of the ASB. Paragraph F(2) of the ASB applies only to helicopters with a copilot collective lever cover.

Differences Between the FAA AD and the MCAI

(g) This AD differs from the MCAI as follows:

(1) We do not require contacting the manufacturer for further instructions if a wiring harness is damaged but require that you replace a damaged wiring harness with an airworthy wiring harness.

(2) We do not require a February 28, 2007, compliance time because that date has passed.

(3) We have used the helicopter S/N 0005 up to and including S/N 0576 as stated in the service information rather than the helicopter S/N 0005 up to and including 0654 as stated in the MCAI.

(4) We refer to the compliance time as "hours TIS" rather than "flight hours."

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Safety Management Group, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Carroll Wright, Aviation Safety Engineer, Rotorcraft Directorate, Regulations and Policy Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5120, fax (817) 222-5961.

(2) Airworthy Product: Use only FAA-approved corrective actions. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent) if the State of Design has an appropriate bilateral agreement with the United States. You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(i) Mandatory Continuing Airworthiness Information (MCAI) Emergency Airworthiness Directive No. 2007-0021-E, dated January 19, 2007, contains related information.

Material Incorporated by Reference

(j) The Director of the Federal Register approved the incorporation by reference of Eurocopter Alert Service Bulletin EC135-53A-017, Revision 1, dated June 22, 2007, under 5 U.S.C. 552(a) and 1 CFR part 51.

(k) For the Eurocopter service information identified in this AD, contact American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527.

(l) You may review copies of the Eurocopter service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas, or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on February 6, 2008.

Scott A. Horn,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. E8-2850 Filed 2-19-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2008-0060; Airspace Docket No. 08-ANE-91]

Establishment of Class E Airspace; Swans Island, ME

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule, request for comments.

SUMMARY: This action establishes Class E Airspace at Swans Island, ME to support a new Area Navigation (RNAV) Global Positioning System (GPS) Special Instrument Approach Procedure (IAP) that has been developed for medical flight operations into the Swans Island Heliport. This action enhances the safety and management of Instrument Flight Rule (IFR) operations by providing that required controlled airspace to protect for this approach around Swans Island, ME.

DATES: Effective 0901 UTC, June 5, 2008. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments. Comments for inclusion in the Rules Docket must be received on or before April 7, 2008.

ADDRESSES: Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2008-0060; Airspace Docket No. 08-ANE-91, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>.

You may review the public docket containing the rule, any comments received, and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays.

An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room 210, 1701 Columbia Avenue, College Park, Georgia 30337.

FOR FURTHER INFORMATION CONTACT:

Melinda Giddens, System Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5610.

SUPPLEMENTARY INFORMATION:**The Direct Final Rule Procedure**

The FAA anticipates that this regulation will not result in adverse or negative comments, and, therefore, issues it as a direct final rule. The FAA has determined that this rule only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Unless a written adverse or negative comment or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the effective date. If the FAA receives, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a direct final rule, and was not preceded by a notice of proposed rulemaking, interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. An electronic copy of this document may be downloaded from and comments may be submitted and reviewed at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov>, or the Federal Register's Web page at <http://www.gpoaccess.gov/fr/index.html>. Communications should identify both docket numbers and be submitted in triplicate to the address specified under the caption **ADDRESSES** above or through the Web site. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. Factual information

that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of this action and determining whether additional rulemaking action would be needed. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. Those wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2008-0060; Airspace Docket No. 08-ANE-91." The postcard will be dated stamped and returned to the commenter.

The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 establishes Class E airspace at Swans Island, ME providing the controlled airspace required to support the new Copter Area Navigation (RNAV) Global Positioning System (GPS) 092 Point in Space (PinS) approach developed for the Swans Island Heliport. In today's environment where speed of treatment for medical injuries is imperative, landing sites have been developed for helicopter medical Lifeguard flights or Lifeflights at the local hospitals; this is one of those sites. Controlled airspace extending upward from 700 feet Above Ground Level (AGL) is required for Instrument Flight Rules (IFR) operations and to encompass all Instrument Approach Procedures (IAPs) to the extent practical, therefore, the FAA is amending Title 14, Code of Federal Regulations (14 CFR) part 71 to establish a 6-mile radius Class E5 airspace at Swans Island, ME. Designations for Class E airspace areas extending upward from 700 feet or more above the surface of the Earth are published in FAA Order 7400.9R, signed August 15, 2007 effective September 15, 2007, which is incorporated by reference in 14 CFR part 71.1. The Class E designations listed in this document will be published subsequently in the Order.

Agency Findings

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation only involves an established

body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace near the Swans Island Heliport in Swans Island, ME.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9R, Airspace Designations and Reporting Points, signed August 15, 2007, effective

September 15, 2007, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward from 700 feet or More Above the Surface of the Earth.

* * * * *

ANE ME E5 Swans Islands, ME [New]

Swans Island Heliport

(Lat. 44°09'55" N., long. 68°25'49" W.)

Point in Space Coordinates

(Lat. 44°09'45" N., long. 68°26'41" W.)

That airspace extending upward from 700 feet above the surface of the Earth within a 6-mile radius of the Point in Space Coordinates (Lat. 44°09'45" N., long. 68°26'41" W.) serving the Swans Island Heliport.

* * * * *

Issued in College Park, Georgia, on January 31, 2008.

Barry A. Knight,

*Acting Manager, System Support Group,
Eastern Service Center.*

[FR Doc. 08-717 Filed 2-19-08; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2008-0063; Airspace
Docket No. 08-ANE-94]

**Establishment of Class E Airspace;
Rumford, ME**

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Direct final rule, request for
comments.

SUMMARY: This action establishes Class E Airspace at Rumford, ME to support a new Area Navigation (RNAV) Global Positioning System (GPS) Special Instrument Approach Procedure (IAP) that has been developed for medical flight operations into the Rumford Community Hospital. This action enhances the safety and management of Instrument Flight Rule (IFR) operations by providing that required controlled airspace to protect for this approach around Rumford, ME.

DATES: Effective 0901 UTC, June 5, 2008. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments. Comments for inclusion in the Rules Docket must be received on or before April 7, 2008.

ADDRESSES: Send comments on this rule to: U.S. Department of Transportation,

Docket Operations, West Building,
Ground Floor, Room W12-140, 1200
New Jersey Avenue, SE., Washington,
DC 20590-0001; Telephone: 1-800-
647-5527; Fax: 202-493-2251. You
must identify the Docket Number FAA-
2008-0063; Airspace Docket No. 08-
ANE-94, at the beginning of your
comments. You may also submit and
review received comments through the
Internet at
<http://www.regulations.gov>.

You may review the public docket
containing the rule, any comments
received, and any final disposition in
person in the Dockets Office (see
ADDRESSES section for address and
phone number) between 9 a.m. and 5
p.m., Monday through Friday, except
Federal Holidays.

An informal docket may also be
examined during normal business hours
at the office of the Eastern Service
Center, Federal Aviation
Administration, Room 210, 1701
Columbia Avenue, College Park, Georgia
30337.

FOR FURTHER INFORMATION CONTACT:

Melinda Giddens, System Support
Group, Eastern Service Center, Federal
Aviation Administration, P.O. Box
20636, Atlanta, Georgia 30320;
telephone (404) 305-5610.

SUPPLEMENTARY INFORMATION:

The Direct Final Rule Procedure

The FAA anticipates that this
regulation will not result in adverse or
negative comments, and therefore,
issues it as a direct final rule. The FAA
has determined that this rule only
involves an established body of
technical regulations for which frequent
and routine amendments are necessary
to keep them operationally current.
Unless a written adverse or negative
comment or a written notice of intent to
submit an adverse or negative comment
is received within the comment period,
the regulation will become effective on
the date specified above. After the close
of the comment period, the FAA will
publish a document in the **Federal
Register** indicating that no adverse or
negative comments were received and
confirming the effective date. If the FAA
receives, within the comment period, an
adverse or negative comment, or written
notice of intent to submit such a
comment, a document withdrawing the
direct final rule will be published in the
Federal Register, and a notice of
proposed rulemaking may be published
with a new comment period.

Comments Invited

Although this action is in the form of
a direct final rule, and was not preceded

by a notice of proposed rulemaking,
interested persons are invited to
comment on this rule by submitting
such written data, views, or arguments
as they may desire. An electronic copy
of this document may be downloaded
from and comments may be submitted
and reviewed at [http://
www.regulations.gov](http://www.regulations.gov). Recently
published rulemaking documents can
also be accessed through the FAA's Web
page at <http://www.faa.gov>, or the
Federal Register's Web page at [http://
www.gpoaccess.gov/fr/index.html](http://www.gpoaccess.gov/fr/index.html).
Communications should identify both
docket numbers and be submitted in
triplicate to the address specified under
the caption **ADDRESSES** above or through
the Web site. All communications
received on or before the closing date
for comments will be considered, and
this rule may be amended or withdrawn
in light of the comments received.

Comments are specifically invited on
the overall regulatory, economic,
environmental, and energy aspects of
the rule that might suggest a need to
modify the rule. Factual information
that supports the commenter's ideas and
suggestions is extremely helpful in
evaluating the effectiveness of this
action and determining whether
additional rulemaking action would be
needed. All comments submitted will be
available, both before and after the
closing date for comments, in the Rules
Docket for examination by interested
persons. Those wishing the FAA to
acknowledge receipt of their comments
submitted in response to this rule must
submit a self-addressed, stamped
postcard on which the following
statement is made: "Comments to
Docket No. FAA-2008-0063; Airspace
Docket No. 08-ANE-94." The postcard
will be date stamped and returned to the
commenter.

The Rule

This amendment to Title 14, Code of
Federal Regulations (14 CFR) part 71
establishes Class E airspace at Rumford,
ME providing the controlled airspace
required to support the new Copter Area
Navigation (RNAV) Global Positioning
System (GPS) 341 Point in Space (PinS)
approach developed for the Rumford
Community Hospital. In today's
environment where speed of treatment
for medical injuries is imperative,
landing sites have been developed for
helicopter medical Lifeguard flights or
Lifeflights at the local hospitals.
Controlled airspace extending upward
from 700 feet Above Ground Level (AGL)
is required for Instrument Flight Rules
(IFR) operations and to encompass all
Instrument Approach Procedures (IAPs)
to the extent practical, therefore, the