

five years each railroad must file a signal system status report. The report is to be prepared on a form issued by FRA in accordance with the instructions and definitions provided. Title 49 of the Code of Federal Regulations, part 235 sets forth the specific conditions under which FRA approval of modification or discontinuance of railroad signal systems is required and prescribes the methods available to seek such approval. The application process prescribed under part 235 provides a vehicle enabling FRA to obtain the necessary information to make logical and informed decisions concerning carrier requests to modify or discontinue signaling systems. Section 235.5 requires railroads to apply for FRA approval to discontinue or materially modify railroad signaling systems. Section 235.7 defines material modifications and identifies those changes that do not require agency approval. Section 235.8 provides that any railroad may petition FRA to seek relief from the requirements under 49 CFR part 236. Sections 235.10, 235.12, and 235.13 describe where the petition must be submitted, what information must be included, the organizational format, and the official authorized to sign the application. Section 235.20 sets forth the process for protesting the granting of a carrier application for signal changes or relief from the rules, standards, and instructions. This section provides the information that must be included in the protest, the address for filing the protest, the item limit for filing the protest, and the requirement that a person requesting a public hearing explain the need for such a forum. Section 236.110 requires that the test results of certain signaling apparatus be recorded and specifically identify the tests required under §§ 236.102–109; 236.377–236.387; 236.576; 236.577; and 236.586–589. Section 236.110 further provides that the test results must be recorded on pre-printed or computerized forms provided by the carrier and that the forms show the name of the railroad, place and date of the test conducted, equipment tested, test results, repairs, and the condition of the apparatus. This section also requires that the employee conducting the test must sign the form and that the record be retained at the office of the supervisory official having the proper authority. Results of tests made in compliance with § 236.587 must be retained for 92 days, and results of all other tests must be retained until the next record is filed, but in no case less than one year. Additionally, § 236.587 requires each railroad to make a

departure test of cab signal, train stop, or train control devices on locomotives before that locomotive enters the equipped territory. This section further requires that whoever performs the test must certify in writing that the test was properly performed. The certification and test results must be posted in the locomotive cab with a copy of the certification and test results retained at the office of the supervisory official having the proper authority. However, if it is impractical to leave a copy of the certification and test results at the location of the test, the test results must be transmitted to either the dispatcher or one other designated official who must keep a written record of the test results and the name of the person performing the test. All records prepared under this section are required to be retained for 92 days. Finally, § 236.590 requires the carrier to clean and inspect the pneumatic apparatus of automatic train stop, train control, or cab signal devices on locomotives every 736 days, and to stencil, tag, or otherwise mark the pneumatic apparatus indicating the last cleaning date.

Type of Request: Revision of a currently approved information collection.

Affected Public: Businesses (Railroads).

Form(s): FRA F 6180.47; FRA F 6180.14.

Total Annual Estimated Responses: 1,673,546.

Total Annual Estimated Burden: 444,883 hours.

Addressee: Send comments regarding these information collections to the Office of Information and Regulatory Affairs, Office of Management and Budget, 725 Seventeenth Street NW., Washington, DC, 20503, Attention: FRA Desk Officer. Comments may also be sent via email to OMB at the following address: oirp_submissions@omb.eop.gov.

Comments are invited on the following: Whether the proposed collections of information are necessary for the proper performance of the functions of the Department, including whether the information will have practical utility; the accuracy of the Department's estimates of the burden of the proposed information collection; ways to enhance the quality, utility, and clarity of the information to be collected; and ways to minimize the burden of the collection of information on respondents, including the use of automated collection techniques or other forms of information technology.

A comment to OMB is best assured of having its full effect if OMB receives it

within 30 days of publication of this notice in the **Federal Register**.

Authority: 44 U.S.C. 3501–3520.

Issued in Washington, DC on August 26, 2015.

Corey Hill,

Acting Executive Director.

[FR Doc. 2015–21542 Filed 8–31–15; 8:45 am]

BILLING CODE 4910–06–P

DEPARTMENT OF TRANSPORTATION

Federal Railroad Administration

[Docket Number FRA–2009–0089]

Petition for Waiver of Compliance

In accordance with part 211 of Title 49 of the Code of Federal Regulations (CFR), this document provides the public notice that by a document posted on March 11, 2015, the Ashtabula, Carson & Jefferson Railroad (ACJR) has petitioned the Federal Railroad Administration (FRA) for a waiver of compliance from certain provisions of the Federal railroad safety regulations contained at 49 CFR 223.11, *Requirements for existing locomotives*. FRA assigned the petition Docket Number FRA–2009–0089.

ACJR of Jefferson City, OH, has petitioned for a permanent waiver of compliance for one locomotive, ACJR 7371, from the requirements of the railroad safety glazing standards at 49 CFR part 223 that require certified glazing in all windows. ACJR, chartered in 1984 to save the Conrail Jefferson Industrial Track, is located in the northeastern corner of Ohio. Its 6.3-mile long track, running through level farmland and wooded areas, has one terminus in Jefferson, OH, and the other, for interchanges, at the south end of Norfolk Southern Railway's Carson Yard in Ashtabula, OH. The railroad provides bulk commodity shipping and transloading services to customers from its staging facilities at the termini. Each year, the railroad hauls approximately 1,200 cars, at speeds not exceeding 10 mph.

The locomotive was built by the American Locomotive Company (Alco) in April 1941, as a model S1 B–B yard switcher with an Alco 539 (6-cylinder, 660 hp) engine. It is equipped with Plexiglas-type safety glazing that is in good condition, clear, and unscratched. ACJR states that there has been no instance of vandalism in approximately 30 years of its operations. ACJR further states that the expense of retrofitting the locomotive to comply with FRA safety glazing standards would impose an

undue financial burden that ACJR cannot bear at this time.

Because of a low risk of exposure to injury due to vandalism and the prohibitive cost of glazing material and labor, ACJR is requesting the waiver of regulation contained at 49 CFR 223.11 for its locomotive listed above.

A copy of the petition, as well as any written communications concerning the petition, is available for review online at www.regulations.gov and in person at the U.S. Department of Transportation's (DOT) Docket Operations Facility, 1200 New Jersey Avenue SE., W12-140, Washington, DC 20590. The Docket Operations Facility is open from 9 a.m. to 5 p.m., Monday through Friday, except Federal Holidays.

Interested parties are invited to participate in these proceedings by submitting written views, data, or comments. FRA does not anticipate scheduling a public hearing in connection with these proceedings since the facts do not appear to warrant a hearing. If any interested party desires an opportunity for oral comment, they should notify FRA, in writing, before the end of the comment period and specify the basis for their request.

All communications concerning these proceedings should identify the appropriate docket number and may be submitted by any of the following methods:

- Web site: <http://www.regulations.gov>. Follow the online instructions for submitting comments.
- Fax: 202-493-2251.
- Mail: Docket Operations Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., W12-140, Washington, DC 20590.
- Hand Delivery: 1200 New Jersey Avenue SE., Room W12-140, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays.

Communications received by October 16, 2015 will be considered by FRA before final action is taken. Comments received after that date will be considered as far as practicable.

Anyone is able to search the electronic form of any written communications and comments received into any of our dockets by the name of the individual submitting the comment (or signing the document, if submitted on behalf of an association, business, labor union, etc.). In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to

better inform its processes. DOT posts these comments, without edit, including any personal information the commenter provides, to www.regulations.gov, as described in the system of records notice (DOT/ALL-14 FDMS), which can be reviewed at www.dot.gov/privacy. See also <http://www.regulations.gov#!/privacyNotice> for the privacy notice of regulations.gov.

Issued in Washington, DC, on August 10, 2015.

Ron Hynes,

Director, Office of Technical Oversight.

[FR Doc. 2015-21526 Filed 8-31-15; 8:45 am]

BILLING CODE 4910-06-P

DEPARTMENT OF TRANSPORTATION

Federal Railroad Administration

[Docket No. FRA-2015-0007-N-21]

Agency Request for Emergency Processing of Collection of Information by the Office of Management and Budget

AGENCY: Federal Railroad Administration (FRA), United States Department of Transportation (USDOT).

ACTION: Notice.

SUMMARY: FRA hereby gives notice that it is submitting the following Information Collection request (ICR) to the Office of Management and Budget (OMB) for Emergency Processing under the Paperwork Reduction Act of 1995. FRA requests that OMB authorize the collection of information identified below seven days after publication of this Notice for a period of 180 days.

FOR FURTHER INFORMATION CONTACT: A copy of this individual ICR, with applicable supporting documentation, may be obtained by telephoning FRA's Office of Safety Clearance Officer: Robert Brogan (tel. (202) 493-6292) or FRA's Office of Administration Clearance Officer: Kimberly Toone (tel. (202) 493-6132); these numbers are not toll-free; or by contacting Mr. Brogan via facsimile at (202) 493-6216 or Ms. Toone via facsimile at (202) 493-6497, or via email by contacting Mr. Brogan at Robert.Broga@dot.gov; or by contacting Ms. Toone at Kim.Toone@dot.gov. Comments and questions about the ICR identified below should be directed to OMB's Office of Information and Regulatory Affairs, Attn: FRA OMB Desk Officer.

SUPPLEMENTARY INFORMATION: FRA issued Safety Advisory 2015-04 on August 20, 2015, to emphasize the importance of timely repairing ballast defects and conditions on main tracks. FRA published Safety Advisory 2015-04 in the **Federal Register** on August 26, 2015. See 80 FR 51868. In the Safety Advisory, FRA notes that ballast defects and ballast conditions that are not repaired in a timely manner can lead to future defects. FRA believes it is important for track inspectors to be aware that ballast defects and conditions can cause track components to deteriorate rapidly and compromise the stability of the track structure, and that inspectors are trained to identify and repair ballast defects and conditions. This safety advisory recommends that track owners and railroads: (1) Assess current engineering instructions on ballast safety and update them to provide specific guidance to track inspectors (designated personnel that are qualified to inspect and repair track) on how to identify and initiate remedial action under 49 CFR 213.233(d) for ballast defects and conditions, as well as on the appropriate remedial action to implement, particularly in areas with one or more additional track conditions; (2) train track inspectors on the updated engineering instructions and this safety advisory to ensure they understand how to identify and initiate remedial action for ballast defects and conditions in a timely manner, and understand the importance of such remedial action in preventing the development of unsafe combinations of track conditions; and (3) ensure that supervisors provide adequate oversight of track inspectors to achieve identification and remediation of ballast defects and other track conditions.

FRA is requesting Emergency processing approval seven days after publication of this **Federal Register** Notice because FRA cannot reasonably comply with normal clearance procedures on account of use of normal clearance procedures is reasonably likely to disrupt the collection of information. The associated collection of information is summarized below.

Title: Ballast Defects and Conditions—Importance of Identification and Repair in Preventing Development of Unsafe Combinations of Track Conditions.

Reporting Burden: