3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under ADDRESSES. Include "AD Docket No. 2003–NE–27–AD" in your request.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

# Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2003–20–07 General Electric Company: Amendment 39–13325. Docket No. 2003–NE–27–AD.

## **Effective Date**

(a) This airworthiness directive (AD) becomes effective November 3, 2003.

#### Affected ADs

(b) None.

#### **Applicability**

(c) This AD applies to General Electric Company (GE) CF6–80E1A2 turbofan engines with forward engine mount platforms part numbers (P/Ns) 1520M53G04 and 1846M24G15 installed. These engines are installed on, but not limited to Airbus Industrie A330 airplanes.

#### **Unsafe Condition**

(d) This AD is prompted by revised analyses of forward engine mount loads by the airframe manufacturer. We are issuing this AD to prevent engine separation that could result from cracking of the forward engine mount platform.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

#### **Platforms Previously Inspected**

(f) For platforms that were inspected using a fluorescent penetrant inspection (FPI) before the effective date of this AD, repeat the FPI within 4,000 cycles-in-service-since last inspection (CSLI).

#### **Platforms Not Previously Inspected**

(g) For platforms that were not inspected using an FPI before the effective date of this AD, inspect the platform using an FPI at the next exposure, or before exceeding 6,360 cycles-since-new (CSN), whichever occurs first.

#### **Platform Repetitive Inspections**

(h) Repeat the FPI within every 4,000 CSLI.

## **Alternative Methods of Compliance**

(i) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

#### Material Incorporated by Reference

(j) None.

#### **Related Information**

(k) GE Aircraft Engines Alert Service Bulletin No. CF6–80E1 S/B 72–A0195 pertains to the subject of this AD. Information on performing FPI can be found in the CF6 component maintenance manual, GEK 99410, section 71–21–02.

Issued in Burlington, Massachusetts, on September 25, 2003.

#### Peter A. White,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service. [FR Doc. 03–25000 Filed 10–2–03; 8:45 am] BILLING CODE 4910–13–P

# **DEPARTMENT OF TRANSPORTATION**

# **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No. FAA-2003-15461; Airspace Docket No. 03-ACE-59]

#### Modification of Class E Airspace; Beatrice, NE

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Direct final rule; confirmation of effective date; rescission of correction.

**SUMMARY:** This document confirms the effective date of the direct final rule which revises Class E airspace at Beatrice, NE. It also rescinds a correction to that final rule.

**EFFECTIVE DATE:** 0901 UTC, October 30, 2003.

# FOR FURTHER INFORMATION CONTACT:

Brenda Mumper, Air Traffic Division, Airspace Branch, ACE–520A, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329–2524.

**SUPPLEMENTARY INFORMATION:** The FAA published this direct final rule with a

request for comments in the Federal Register on July 31, 2003 (68 FR 44875) and subsequently published a correction to the direct final rule in the Federal Register on September 9, 2003 (68 FR 53034). Information in the original publication is accurate. The correction was inadvertently published and is hereby rescinded.

The FAA uses the direct final rulemaking procedure for a noncontroversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on October 30, 2003. No adverse comments were received, and thus this notice confirms that this direct final rule will become effective on that date.

Dated: Issued in Kansas City, MO on September 19, 2003.

#### David W. Hope,

Acting Manager, Air Traffic Division, Central Region.

[FR Doc. 03–25049 Filed 10–2–03; 8:45 am]
BILLING CODE 4910–13–M

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 97

[Docket No. 30390; Amdt. No. 3077]

# Standard Instrument Approach Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes. amends, suspends, or revokes Standard **Instrument Approach Procedures** (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective October 3, 2003. The compliance date for each

SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 3, 2003.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

- 1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
- 2. The FAA Regional Office of the region in which the affected airport is located:
- 3. The Flight Inspection Area Office which originated the SIAP; or,
- 4. The Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

For Purchase—Individual SIAP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription—Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

## FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS–420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954–4164.

**SUPPLEMENTARY INFORMATION: This** amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260-3, 8260-4, and 8260-5. Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a

special format make their verbatim publication in the Federal Register expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

#### The Rule

This amendment to part 97 is effective upon publication of each separate SIAP as contained in the transmittal. Some SIAP amendments may have been previously issued by the FAA in a National Flight Data Center (NFDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP amendments may require making them effective in less than 30 days. For the remaining SIAPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for **Terminal Instrument Procedures** (TERPS). In developing these SIAPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making some SIAPs effective in less than 30 days.

#### Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same

reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 97

Air Traffic Control, Airports, Incorporation by reference, and Navigation (Air).

Issued in Washington, DC, on September 26, 2003.

# James J. Ballough,

Director, Flight Standards Service.

#### Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me, part 97 of the Federal Aviation Regulations (14 CFR part 97) is amended by establishing, amending, suspending, or revoking Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

# PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

- 2. Part 97 is amended to read as follows:
- \* \* \* Effective October 30, 2003

Susanville, CA, Susanville Muni, RNAV (GPS)–A, Orig

Susanville, CA, Susanville Muni, RNAV (GPS) Rwy 29, Orig

Orlando, FL, Executive, VOR/DME Rwy 25, Amdt 2

Orlando, FL, Executive, VOR/DME Rwy 7, Amdt 1

Orlando, FL, Executive, LOC BC Rwy 25,

Orlando, FL, Executive, NDB Rwy 7, Amdt

Orlando, FL, Executive, ILS OR LOC Rwy 7, Amdt 22

Orlando, FL, Executive, RNAV (GPS) Rwy 7, Orig

Orlando, FL, Executive, GPS Rwy 7, Orig–A, Cancelled

Orlando, FL, Executive, GPS Rwy 25, Orig— C, Cancelled

Orlando, FL, Executive, RNAV (GPS) Rwy 25, Orig

Indianapolis, IN, Indianapolis Brookside Airpark, VOR OR GPS Rwy 36, Amdt 6, Cancelled

Elkhart, KS, Elkhart-Morton County, RNAV (GPS) Rwy 4, Orig

Elkhart, KS, Elkhart-Morton County, RNAV (GPS) Rwy 17, Orig

Elkhart, KS, Elkhart-Morton County, RNAV (GPS) Rwy 22, Orig

Elkhart, KS, Elkhart-Morton County, RNAV (GPS) Rwy 35, Orig

Elkhart, KS, Elkhart-Morton County, NDB Rwy 35, Amdt 1

- Lake Providence, LA, Byerley, NDB Rwy 17, Amdt 2
- Ogdensburg, NY, Ogdensburg Intl, RNAV
- (GPS) Rwy 27, Orig Ogdensburg, NY, Ogdensburg Intl, LOC Rwy 27, Amdt 2
- Ogdensburg, NY, Ogdensburg Intl, NDB Rwy 27. Amdt 1
- Williamson/Sodus, NY, Williamson-Sodus, RNAV (GPS) Rwy 10, Orig
- Williamson/Sodus, NY, Williamson-Sodus, RNAV (GPS) Rwy 28, Orig
- Williamson/Sodus, NY, Williamson-Sodus, GPS Rwy 28, Orig, Cancelled
- Corpus Christi, TX, Corpus Christi Intl, RNAV (GPS) Rwy 31, Orig-A
- Harlingen, TX, Valley Intl, LOC BC Rwy 35L, Amdt 13A, Cancelled
- \* \* \* Effective December 25, 2003

Kenai, AK, Kenai Muni, NDB-A, Amdt 3B Rayville, LA, John H. Hooks Jr. Memorial, NDB Rwy 36, Amdt 2

- North Myrtle Beach, SC, Grand Strand, NDB Rwy 23, Amdt 11
- North Myrtle Beach, SC, Grand Strand, VOR Rwy 5, Amdt 21
- Lubbock, TX, Lubbock Intl, VOR/DME RNAV Rwy 8, Amdt 2A, Cancelled

[FR Doc. 03-25053 Filed 10-2-03; 8:45 am] BILLING CODE 4910-13-P

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 97

[Docket No. 30391; Amdt. No. 3078]

#### Standard Instrument Approach **Procedures: Miscellaneous Amendments**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective October 3, 2003. The compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 3, 2003.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination

- 1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
- 2. The FAA Regional Office of the region in which affected airport is located: or
- 3. The Flight Inspection Area Office which originated the SIAP.
- 4. The Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

For Purchase—Individual SIAP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription—Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT: Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK. 73125) telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION: This** amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and section 97.20 of the Federal Aviation's Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the Federal Register expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials.

Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

#### The Rule

This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes SIAPs. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained in the content of the following FDC/P NOTAMs for each SIAP. The SIAP information in some previously designated FDC/Temporary (FDC/T) NOTAMs is of such duration as to be permanent. With conversion to FDC/P NOTAMs, the respective FDC/T NOTAMs have been canceled.

The FDC/P NOTAMs for the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these chart changes to SIAPs by FDC/P NOTAMs, the TERPS criteria were applied to only these specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a National Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for all these SIAP amendments requires making them effective in less than 30 days.

Further, the SIAPs contained in this amendment are based on the criteria contained in the TERPS. Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making these SIAPs effective in less than 30 days.

#### Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT