

ARFF Vehicle
Remove Existing Maintenance
Building
ADA Lift Device
General Aviation Terminal
Construction
General Aviation Terminal Access
Road & Parking
Emergency Response Vehicle
Air Carrier Apron Expansion
PFC Amendment/Application
Development
PFC Program Administration

Class or classes of air carriers which the public agency has requested not be required to collect PFCs: None.

Any person may inspect the application in person at the FAA office listed above under **FOR FURTHER INFORMATION CONTACT**.

In addition, any person may, upon request, inspect the application, notice and other documents germane to the application in person at the Albert J. Ellis Airport.

Issued in College Park, Georgia, on September 30, 2004.

Scott L. Seritt,

Manager, Atlanta Airports District Office, Southern Region.

[FR Doc. 04-22618 Filed 10-7-04; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

Notice of Intent To Rule on Application To Impose and Use the Revenue From a Passenger Facility Charge (PFC) at T. F. Green State Airport, Warwick, Rhode Island, for Projects at T. F. Green State Airport, Warwick, Rhode Island; North Central State Airport, Smithfield, Rhode Island; Quonset State Airport, North Kingstown, Rhode Island; and Westerly State Airport, Westerly, Rhode Island

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of intent to rule on application.

SUMMARY: The FAA proposes to rule and invites public comment on the application to use the revenue from a PFC at T. F. Green State Airport under the provisions of 49 U.S.C. 40117 and part 158 of the Federal Aviation Regulations (14 CFR part 158).

DATES: Comments must be received on or before November 8, 2004.

ADDRESSES: Comments on this application may be mailed or delivered in triplicate to the FAA at the following address: Federal Aviation Administration, Airports Division, 12

New England Executive Park, Burlington, Massachusetts 01803.

In addition, one copy of any comments submitted to the FAA must be mailed or delivered to Mr. Brian C. Schattle, at the following address: Vice President Finance/CFO, Rhode Island Aviation Corporation, T. F. Green State Airport, 2000 Post Road, Warwick, Rhode Island, 02886.

Air carriers and foreign air carriers may submit copies of written comments previously provided to the Rhode Island Airport Corporation under section 158.23 of part 158 of the Federal Aviation Regulations.

FOR FURTHER INFORMATION CONTACT:

Priscilla A. Scott, PFC Program Manager, Federal Aviation Administration, Airports Division, 12 New England Executive Park, Burlington, Massachusetts.

SUPPLEMENTARY INFORMATION: The FAA proposes to rule and invites public comment on the application to use the revenue from a PFC at T. F. Green State Airport under the provisions of the Aviation Safety and Capacity Expansion Act of 1990 (Title IX of the Omnibus Budget Reconciliation Act of 1990)(Public Law 101-508) and part 158 of the Federal Aviation Regulations (14 CFR part 158).

On August 20, 2004, the FAA determined that the application to use the revenue from a PFC submitted by Rhode Island Airport Corporation was substantially complete within the requirements of section 158.25 of part 158. The FAA will approve or disapprove the application, in whole or in part, no later than November 18, 2004.

The following is a brief overview of the application.

PFC Project #: 04-04-U-00-PVD.

Level of the proposed PFC: \$3.00.

Charge effective date: April 1, 2008.

Estimated charge expiration date:

August 1, 2012.

Total estimated PFC revenue:

\$19,855,000.

Brief description of proposed use projects: T.F. Green State Airport, New Airfield Maintenance Facility, Ticket Counter Expansion; North Central State Airport, Rehabilitation of Apron; Quonset State Airport, Rehabilitation of Apron; and Westerly State Airport, Rehabilitation of Apron and Taxiways B and C.

Class or classes of air carriers, which the public agency has requested to be required to collect PFCs: On demand Air Taxi/Commercial Operators (ATCO).

Any person may inspect the application in person at the FAA office listed above under **FOR FURTHER INFORMATION CONTACT**.

In addition, any person may, upon request, inspect the application, notice and other documents germane to the application in person at the Rhode Island Airport Corporation.

Issued in Burlington, Massachusetts on September 21, 2004.

Vincent A. Scarano,

Manager, Airports Division, New England Region.

[FR Doc. 04-22748 Filed 10-7-04; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Railroad Administration

Agency Information Collection Activities

AGENCY: Federal Railroad Administration, DOT.

ACTION: Notice of OMB approvals.

SUMMARY: In compliance with the Paperwork Reduction Act of 1995 (44 U.S.C. 3501 *et seq.*) and 5 CFR 1320.5(b), this notice announces that new information collections requirements (ICRs) listed below have been approved by the Office of Management and Budget (OMB). These new ICRs pertain to 49 CFR parts 219 and 222. Additionally, FRA hereby announces that other ICRs listed below have been re-approved by the Office of Management and Budget (OMB). These ICRs pertain to parts 213, 215, 216, 223, 229, and 239. The OMB approval numbers, titles, and expiration dates are included herein under supplementary information.

FOR FURTHER INFORMATION CONTACT: Mr. Robert Brogan, Office of Planning and Evaluation Division, RRS-21, Federal Railroad Administration, 1120 Vermont Ave., NW., Mail Stop 17, Washington, DC 20590 (telephone: (202) 493-6292), or Debra Steward, Office of Information Technology and Productivity Improvement, RAD-20, Federal Railroad Administration, 1120 Vermont Ave., NW., Mail Stop 35, Washington, DC 20590 (telephone: (202) 493-6139). (These telephone numbers are not toll-free.)

SUPPLEMENTARY INFORMATION: The Paperwork Reduction Act of 1995 (PRA), Pub. L. 104-13, section 2, 109 Stat. 163 (1995) (codified as revised at 44 U.S.C. 3501-3520), and its implementing regulations, 5 CFR part 1320, require Federal agencies to display OMB control numbers and inform respondents of their legal significance once OMB approval is obtained. The following new FRA information collections were approved:

(1) OMB No. 2130-0560, Use of Locomotive Horns at Highway-Rail Grade Crossings (49 CFR part 222) (Interim Final Rule). The expiration date for this information collection is April 30, 2007. (2) OMB No. 2130-0561, Work Schedules and Sleep Patterns of Maintenance of Way Employees (Forms FRA F 6180.114/115). The expiration date for this information collection is May 31, 2007. (3) OMB No. 2130-0555, Foreign-Railroad Foreign-Based (FRFB) Employees Who Perform Train or Dispatching Service in the United States (49 CFR 219) (Final Rule). The expiration date for this information collection is July 31, 2007.

The following information collections were re-approved: (1) OMB No. 2130-0010, Track Safety Standards (Gage Restraint Measurement Systems) (49 CFR 213). The new expiration date for this information collection is June 30, 2007. (2) OMB No. 2130-0504, Special Notice for Repairs (49 CFR 216). The new expiration date for this information collection is July 31, 2007. (3) OMB No. 2130-0511, Designation of Qualified Persons (49 CFR 215). The new expiration date for this information collection is June 30, 2007. (4) OMB No. 2130-0545, Passenger Train Emergency Preparedness (49 CFR parts 223 and 239). The new expiration date for this information collection is May 31, 2007. (5) OMB No. 2130-0004, Locomotive Safety Standards and Event Recorders (49 CFR part 229). The new expiration date for this information collection is September 30, 2007.

Persons affected by the above referenced information collections are not required to respond to any collection of information unless it displays a currently valid OMB control number. These approvals by the Office of Management and Budget (OMB) certify that FRA has complied with the provisions of the Paperwork Reduction Act of 1995 (Pub. L. 104-13) and with 5 CFR 1320.5(b) by informing the public about OMB's approval of the information collection requirements of the above cited forms and regulations.

Authority: 44 U.S.C. 3501-3520.

Issued in Washington, DC, on September 30, 2004.

Kathy A. Weiner,

Director, Office of Information Technology and Support Systems, Federal Railroad Administration.

[FR Doc. 04-22620 Filed 10-7-04; 8:45 am]

BILLING CODE 4910-06-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2004-19217; Notice 1]

Mitsubishi Motor Sales Caribbean, Inc., Receipt of Petition for Decision of Inconsequential Noncompliance

Mitsubishi Motor Sales Caribbean, Inc. (MMSC) has determined that certain vehicles that it imported and distributed in 1997 through 2005 do not comply with S4.5.1(b)(2)(ii), (c)(1) and (e)(1)(ii) of 49 CFR 571.208, Federal Motor Vehicle Safety Standard (FMVSS) No. 208, "Occupant Crash Protection." MMSC has filed an appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports."

Pursuant to 49 U.S.C. 30118(d) and 30120(h), MMSC has petitioned for an exemption from the notification and remedy requirements of 49 U.S.C. chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of MMSC's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

A total of approximately 85,065 model year 1998 to 2005 Mitsubishi vehicles are affected. Approximately 70,592 Monteros, Nativas, Diamantes, Mirages, Lancers, and Outlanders covering model years from 1998 to 2005 do not comply with S4.5.1(b)(2)(ii), "Sun visor air bag warning label." Approximately 10,761 Nativas covering model years 2000-2004 do not comply with S4.5.1(c)(1), "Air bag alert label." Approximately 85,065 Monteros, Nativas, Diamantes, Mirages, Lancers, 3000 GTs, Outlanders, Galants, Eclipses, Eclipse Spyders, and Endeavors covering model years 1998-2005 do not comply with S4.5.1(e)(1)(ii), "Label on the dashboard."

The relevant requirements of FMVSS No. 208, S4.5.1, "Labeling and owner's manual information," are as follows: "(b)(2)(ii) The message area [of the permanent sun visor air bag warning label] * * * shall be no less than 30 cm². * * * (c)(1) The message area [of the permanent sun visor air bag alert label] * * * shall be no less than 20 square cm. * * * (e)(1)(ii) The message area [of the temporary label on the dashboard] * * * shall be no less than 30 cm²."

On the affected vehicles, the actual measurement of the English message area for the sun visor air bag warning label is 27 cm² rather than the required

minimum of 30 cm², for the sun visor alert label is 12 cm² rather than the required minimum of 20 cm², and for the dash label is 19 cm² rather than the required minimum of 30 cm². MMSC explains that these noncompliances resulted from reducing the English message areas when the respective Spanish translations were added.

MMSC believes that the noncompliance is inconsequential to motor vehicle safety and that no corrective action is warranted. In support of its petition, MMSC states the following:

The likelihood consumers will perceive the presence of the labels is enhanced since the overall sizes of the bilingual labels are larger than the English only labels while the understandability performance of the warnings is enhanced since the message reaches a wider audience than an English only version.

The legibility of the labels at the required distance (*i.e.*, from all front seating positions) is not degraded since the font size, font color, and letter spacing remain the same as our English only versions that meet the message area requirements.

The labels meet all other requirements in every respect including heading content, heading color, message content, message area color, message text color, alert symbol content, and alert symbol color. * * *

Mitsubishi believes the percentage of vehicles actually fitted today with the non-compliant temporary dash labels is for all intents and purposes zero, considering in all likelihood they have already been removed by customers after purchase.

MMSC has received no customer complaints related to the bilingual labels.

Interested persons are invited to submit written data, views, and arguments on the petition described above. Comments must refer to the docket and notice number cited at the beginning of this notice and be submitted by any of the following methods. Mail: Docket Management Facility, U.S. Department of Transportation, Nassif Building, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590-0001. Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC. It is requested, but not required, that two copies of the comments be provided. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except Federal holidays. Comments may be submitted electronically by logging onto the Docket Management System Web site at <http://dms.dot.gov>. Click on "Help" to obtain instructions for filing the document electronically. Comments may be faxed to 1-202-493-2251, or may be submitted to the Federal