

(516) 287-7329; fax: (516) 794-5531; email: [aziz.ahmed@faa.gov](mailto:aziz.ahmed@faa.gov).

#### SUPPLEMENTARY INFORMATION:

Airworthiness Directive 2016-10-03, Amendment 39-18514 (81 FR 29125, May 11, 2016), requires removing whichever previous revision of the Otter Baron short take-off and landing (STOL) kit installation flight manual supplement (FMS) that is currently being used and incorporate Stolairus Aviation Inc. Flight Manual Supplement #4 for de Havilland DHC-3 Otter with the Baron STOL Kit Installation, Revision 3, dated May 22, 2015, for Viking Air Limited Model DHC-3 airplanes that are modified with the Baron Short Take Off and Landing (STOL) kit (Supplemental Type Certificate SA94-114 or SA 00287NY).

As published, the Code of Federal Regulations (CFR) reference for records maintenance cited in the last sentence in paragraph (f) is incorrect. The published reference is 14 CFR 91.173 or 135.439, and it should be 14 CFR 91.417, 121.380, or 135.439.

Although no other part of the preamble or regulatory information has been corrected, we are publishing the entire rule in the **Federal Register**.

The effective date of this AD remains May 31, 2016.

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

#### 2016-10-03 Viking Air Limited:

Amendment 39-18514; Docket No. FAA-2016-6628; Directorate Identifier 2016-CE-013-AD.

#### (a) Effective Date

This airworthiness directive (AD) becomes effective May 31, 2016.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Viking Air Limited Model DHC-3 airplanes, all serial numbers, that are:

- (1) Modified with the Baron Short Take Off and Landing (STOL) kit (Supplemental Type Certificate SA94-114 or SA 00287NY); and
- (2) certificated in any category.

#### (d) Subject

Air Transport Association of America (ATA) Code 8: Leveling and Weighing.

#### (e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI)

originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as an accident report that indicated that the center of gravity was too far aft and contributed to a stall during takeoff. We are issuing this AD to correct the center of gravity and prevent such a stall during takeoff and loss of control during other phases of flight.

#### (f) Actions and Compliance

Unless already done, within 30 days after May 31, 2016 (the effective date of this AD), remove whichever previous revision of the Otter Baron short take-off and landing (STOL) kit installation flight manual supplement (FMS) that is currently being used and incorporate Stolairus Aviation Inc. Flight Manual Supplement #4 for de Havilland DHC-3 Otter with the Baron STOL Kit Installation, Revision 3, dated May 22, 2015. This action may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9(a)(1)–(4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

#### (g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Aziz Ahmed, Aerospace Engineer, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: (516) 287-7329; fax: (516) 794-5531; email: [aziz.ahmed@faa.gov](mailto:aziz.ahmed@faa.gov). Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

#### (h) Related Information

Refer to MCAI Transport Canada AD CF-2016-05, dated January 25, 2016, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6628.

#### (i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Stolairus Aviation Inc., Flight Manual Supplement #4, de Havilland DHC-3 Otter, Baron STOL Kit Installation, DOT STC # SA 94-114/FAA STC # SA 00287 NY, Revision 3, dated May 22, 2015.

(ii) Reserved.

(3) For Stolairus Aviation Inc. service information identified in this AD, contact Stolairus Aviation Inc. (formerly known as AOG Air Support, Inc.), 6095 Airport Way, Kelowna, British Columbia V1V 1S1; phone: (250) 491-7511; fax: (25) 491-7522; Internet: <http://www.stolairus.com>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for locating Docket No. FAA-2016-6628.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on May 20, 2016.

**Pat Mullen,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016-12468 Filed 5-26-16; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF STATE

### 22 CFR Part 171

[Public Notice: 9523]

RIN 1400-AD88

### Privacy Act; STATE-81, Office of Foreign Missions Records

**AGENCY:** Department of State.

**ACTION:** Final rule.

**SUMMARY:** The Department of State is issuing a final rule to amend its Privacy Act regulation exempting portions of a system of records from one or more provisions of the Privacy Act of 1974.

**DATES:** This final rule is effective May 27, 2016.

#### FOR FURTHER INFORMATION CONTACT:

William P. Fischer, Acting Director; Office of Information Programs and Services, A/GIS/IPS; Department of State, SA-2; 515 22nd Street NW., Washington, DC 20522-8001, or at [Privacy@state.gov](mailto:Privacy@state.gov).

**SUPPLEMENTARY INFORMATION:** The system, Office of Foreign Missions Records, designated as STATE-81, supports the Office of Foreign Missions, Department of State, in the implementation of the Foreign Missions

Act, the operation of foreign missions, and the United States' extension of privileges, exemptions, immunities, benefits, and courtesies to foreign government officials, members/employees and officers of foreign missions and certain international organizations in the United States, their immediate family members, and domestic workers who are in the United States in nonimmigrant A-3 or G-5 visa status.

For additional background, see the notice of proposed rulemaking and the system of records notice published on December 17, 2015 (80 FR 78704 and 80 FR 78812, respectively). The Department received no public comment on these documents.

#### List of Subjects in 22 CFR Part 171

Privacy.

For the reasons stated in the preamble, 22 CFR part 171 is amended as follows:

#### PART 171—[AMENDED]

- 1. The authority citation for part 171 continues to read as follows:

**Authority:** 22 U.S.C. 2651a; 5 U.S.C. 552; 552a; E.O. 12600 (52 FR 23781); Pub. L. 95–521, 92 Stat. 1824 (codified as amended as 5 U.S.C. app. 101–505); 5 CFR part 2634.

#### § 171.26—[Amended]

- 2. Section § 171.26 is amended by adding an entry, in alphabetical order, for “Office of Foreign Missions Records, STATE–81” to the list in paragraph (b)(2).

Joyce A. Barr,

*Assistant Secretary for Administration, U.S. Department of State.*

[FR Doc. 2016–12621 Filed 5–26–16; 8:45 am]

BILLING CODE 4710–43–P

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[Docket No. USCG–2015–1011]

RIN 1625–AA09

#### Drawbridge Operation Regulation; Broad Creek, Laurel, DE

**AGENCY:** Coast Guard, DHS.

**ACTION:** Final rule.

**SUMMARY:** The Coast Guard is changing the regulation that governs the operation of the Norfolk Southern Railroad Bridge over Broad Creek, mile 8.0, at Laurel, DE. This final rule changes the current

regulation requiring a four-hour advance notice and allows the bridge to remain in the closed to navigation position. This final rule aligns the operating schedule with the observed lack of marine traffic that requires a bridge opening and the operating regulations for the Poplar Street and US Highway 13A, which also cross Broad Creek.

**DATES:** This rule is effective June 27, 2016.

**ADDRESSES:** To view documents mentioned in this preamble as being available in the docket, go to <http://www.regulations.gov>, type USCG 2015–1011 in the “SEARCH” box and click “SEARCH.” Click on Open Docket Folder on the line associated with this rulemaking.

**FOR FURTHER INFORMATION CONTACT:** If you have questions on this rule, call or email Mrs. Jessica Shea, Fifth Coast Guard District (dpb), at (757) 398–6422, email [jessica.c.shea2@uscg.mil](mailto:jessica.c.shea2@uscg.mil).

#### SUPPLEMENTARY INFORMATION:

##### I. Table of Abbreviations

CFR Code of Federal Regulations  
DHS Department of Homeland Security  
E.O. Executive order  
FR Federal Register  
NPRM Notice of proposed rulemaking  
Pub. L. Public Law  
§ Section  
U.S.C. United States Code

##### II. Background Information and Regulatory History

On February 3, 2016, we published a notice of proposed rulemaking (NPRM) entitled Drawbridge Operation Regulation; Broad Creek, Laurel, DE in the **Federal Register** (81 FR 5679). We received one comment on this rule.

##### III. Legal Authority and Need for Rule

The Coast Guard is issuing this rule under authority 33 U.S.C. 499. The bridge owner, Norfolk Southern, made a request under 33 CFR 117.39 that the operating regulations be revised due to infrequent openings. The Norfolk Southern Railroad Bridge over Broad Creek, mile 8.0, at Laurel, DE, is a swing bridge that has a vertical clearance of fourteen feet above mean high water in the closed to navigation position and is unlimited in the open to navigation position.

Presently, the bridge opens with 4 hour advance notice in accordance with 33 CFR 117.233(a). This final rule changes the status of the Norfolk Southern Broad Creek railroad bridge to need not open for the passage of vessels. There have been no requests for openings from vessels since Norfolk Southern acquired the bridge in 1999. In order to align the operating schedule of

the bridge with observed marine traffic, this change amends the regulation to state that the bridge need not open. The lack of requests from vessels for bridge openings since 1999 illustrate that the vessels that use this waterway can safely navigate while the drawbridge is in the closed-to-navigation position.

#### IV. Discussion of Comments, Changes and the Final Rule

One comment was made in response to the NPRM. The comment was in favor of the need not open status. There were no changes made to the final rule from what was proposed in the NPRM.

This rule changes the status of the Norfolk Southern Railroad Bridge to need not open for the passage of vessels. This action aligns the operating schedule of the bridge with the lack observed marine traffic that requires an opening and with the operating schedule for other drawbridges on this waterway. The change amends the regulation to state that the bridge need not open.

#### V. Regulatory Analyses

We developed this rule after considering numerous statutes and Executive Orders related to rulemaking. Below we summarize our analyses based on a number of these statutes and Executive Orders, and we discuss First Amendment rights of protesters.

##### A. Regulatory Planning and Review

Executive Orders 12866 and 13563 direct agencies to assess the costs and benefits of available regulatory alternatives and, if regulation is necessary, to select regulatory approaches that maximize net benefits. Executive Order 13563 emphasizes the importance of quantifying both costs and benefits, of reducing costs, of harmonizing rules, and of promoting flexibility. This rule has not been designated a “significant regulatory action,” under Executive Order 12866. Accordingly, it has not been reviewed by the Office of Management and Budget. This regulatory action determination is based on the observed lack of marine traffic that requires a bridge opening.

##### B. Impact on Small Entities

The Regulatory Flexibility Act of 1980 (RFA), 5 U.S.C. 601–612, as amended, requires federal agencies to consider the potential impact of regulations on small entities during rulemaking. The term “small entities” comprises small businesses, not-for-profit organizations that are independently owned and operated and are not dominant in their fields, and governmental jurisdictions