(i) New Repair Requirement

If any crack is detected during any inspection required by paragraph (h) of this AD: Before further flight, repair, including doing all applicable related investigative actions, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-53-1089, Revision 03, dated March 18, 2015. Do all applicable related investigative actions before further flight. Repair of an airplane in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-53-1089, Revision 03, dated March 18, 2015, constitutes terminating action for the repetitive inspections required by paragraph (h) of this AD.

(j) New Optional Modification

Modification of an airplane, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–53–1090, Revision 02, dated December 22, 1998, constitutes terminating action for the repetitive inspections required by paragraph (h) of this AD, provided the modification is accomplished before further flight after accomplishing an inspection required by paragraph (h) of this AD and no cracks were detected.

(k) Credit for Previous Actions

- (1) This paragraph provides credit for actions required by paragraphs (h) and (i) of this AD, if those actions were performed before the effective date of this AD using the service information identified in paragraphs (k)(1)(i) and (k)(1)(ii) of this AD, which are not incorporated by reference in this AD.
- (i) Airbus Service Bulletin A320–53–1089, Revision 01, dated June 4, 1998;
- (ii) Airbus Service Bulletin A320–53–1089, Revision 02, dated February 3, 2003.
- (2) This paragraph provides credit for the actions required by paragraph (j) of this AD, if those actions were performed before the effective date of this AD in accordance with the service information identified in paragraphs (k)(2)(i) and (k)(2)(ii) of this AD.
- (i) Airbus Service Bulletin A320–53–1090, dated November 22, 1995, which was incorporated by reference in AD 98–13–14, Amendment 39–10602 (63 FR 34556, June 25, 1998).
- (ii) Airbus Service Bulletin A320–53–1090, Revision 1, dated November 22, 1995, dated June 10, 1998, which is not incorporated by reference in this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind

Avenue SW., Renton, WA 98057–3356; telephone 425–227–1405; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOG-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

- (2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM—116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.
- (3) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Related Information

- (1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2015–0084, dated May 13, 2015; corrected May 18, 2015, for related information. This MCAI may be found in the AD docket on the Internet at http://www.regulations.gov by searching for and locating Docket No. FAA–2016–7262.
- (2) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet http://www.airbus.com. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on June 3, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 2016–14301 Filed 6–20–16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2014-0726; Airspace Docket No. 14-ASO-9]

Proposed Amendment of Class D and E Airspace, and Revocation of Class E Airspace; Troy, AL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class D and E airspace, and remove Class E airspace designated as an extension at Troy Municipal Airport at N. Kenneth Campbell Field (formerly Troy Municipal Airport), Troy, AL. The Troy VHF Omnidirectional Radio Range (VOR) has been decommissioned, therefore Class E extension airspace is no longer needed, and new Standard Instrument Approach Procedures have been developed for Class D airspace and Class E airspace extending upward from 700 feet above the surface at the airport. This action would enhance the safety and airspace management of Instrument Flight Rules (IFR) operations at the airport. This action also would update the geographic coordinates of the airport and recognize the name change of the airport.

DATES: Comments must be received on or before August 5, 2016.

ADDRESSES: Send comments on this proposal to: U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Bldg Ground Floor Rm W12-140, Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2014-0726; Airspace Docket No. 14–ASO–9, at the beginning of your comments. You may also submit and review received comments through the Internet at http:// www.regulations.gov. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at http://www.faa.gov/airtraffic/publications/. For further information,

you can contact the Airspace Policy Group, Federal Aviation
Administration, 800 Independence
Avenue SW., Washington, DC 20591;
telephone: 202–267–8783. The Order is
also available for inspection at the
National Archives and Records
Administration (NARA). For
information on the availability of FAA
Order 7400.9Z at NARA, call 202–741–
6030, or go to http://www.archives.gov/
federal_register/code_of_federalregulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I. Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, Part, A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would amend Class E airspace at Troy Municipal Airport at N. Kenneth Campbell Field, Troy, AL.

Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2014–0726; Airspace Docket No. 14–ASO–9) and be submitted in triplicate to the Docket Management System (see ADDRESSES section for address and phone number). You may also submit

comments through the Internet at http://www.regulations.gov.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2014-0726; Airspace Docket No. 14-ASO-9." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through http://www.regulations.gov. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the ADDRESSES section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal Holidays at the office of the Eastern Service Center, Federal Aviation Administration, Room 350, 1701 Columbia Avenue, College Park, Georgia 30337. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory circular No. 11–2A, Notice of Proposed Rulemaking distribution System, which describes the application procedure.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the ADDRESSES section of this document. FAA Order 7400.9Z lists Class A, B, C,

D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to amend Class E airspace extending upward from 700 feet above the surface, at Troy Municipal Airport at N. Kenneth Campbell Field, formerly Troy Municipal Airport, Troy, AL, as new Standard Instrument Approach Procedures have been developed requiring airspace redesign. Additionally, Class E airspace designated as an extension to Class D surface area would be removed due to the decommissioning of the Troy VOR and cancellation of the VOR approaches. For the Class D and E airspace areas above the geographic coordinates of the airport would be amended to coincide with the FAAs aeronautical database. This action is necessary for continued safety and management of IFR operations at the airport.

Class D and E airspace designations are published in Paragraphs 5000, 6004 and 6005, respectively, of FAA Order 7400.9Z, dated August 6, 2015, and effective September 15, 2015, which is incorporated by reference in 14 CFR 71.1. The Class D and E airspace designations listed in this document will be published subsequently in the Order.

Regulatory Notices and Analyses

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

This proposal would be subject to an environmental analysis in accordance with FAA Order 1050.1F, paragraph 5.6.5a, "Environmental Impacts:

Policies and Procedures" prior to any FAA final regulatory action.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f),106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, effective September 15, 2015, is amended as follows:

Paragraph 5000 Class D Airspace

ASO AL D Troy, AL [Amended]

Troy Municipal Airport at N. Kenneth Campbell Field, AL (Lat. 31°51′36″ N., long. 86°00′50″ W.)

That airspace extending upward from the surface to and including 2,900 feet MSL within a 5-mile radius of Troy Municipal Airport at N. Kenneth Campbell Field. This Class D airspace area is effective during specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

Paragraph 6004 Class E Airspace Designated as an Extension to a Class D Surface Area.

ASO AL E4 Troy, AL [Removed]

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

ASO AL E5 Troy, AL [Amended]

Troy Municipal Airport at N. Kenneth Campbell Field, AL

(Lat. 31°51′36″ N., long. 86°00′50″ W.) That airspace extending upward from 700 feet above the surface within a 7.6-mile radius of Troy Municipal Airport at N. Kenneth Campbell Field and within 2-miles each side of a 070° bearing from the airport to 11.5-miles northeast of the airport, and within 2-miles each side of a 253° bearing from the airport to 11.3-miles southwest of the airport.

Issued in College Park, Georgia, on June 9, 2016.

Ryan W. Almasy,

Manager, Operation Support Group, Eastern Service Center, Air Traffic Organization. [FR Doc. 2016–14374 Filed 6–20–16; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2016-5444; Airspace Docket No. 16-ANE-1]

Proposed Amendment of Class D and E Airspace, Falmouth, MA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace designated as an extension at Cape Cod Coast Guard Air Station, (formerly Otis ANGB) Falmouth, MA, as the Otis TACAN has been decommissioned, requiring airspace reconfiguration. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations at the airport. This action also would update the geographic coordinates of the airport in the existing Class D and E airspace areas, as well as Falmouth Airpark, Barnstable Municipal Airport-Boardman/Polando Field, Chatham Municipal Airport, Martha's Vineyard Airport, (formerly Martha's Vineyard Municipal Airport), and the BOGEY LOM.

DATES: Comments must be received on or before August 5, 2016.

ADDRESSES: Send comments on this rule to: U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Bldg Ground Floor Rm W12-140, Washington, DC 20591 0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2016-5444; Airspace Docket No. 16–ANE–1, at the beginning of your comments. You may also submit and review received comments through the Internet at http:// www.regulations.gov. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at http://www.faa.gov/airtraffic/ publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202-267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.9Z at NARA, call 202-741-6030, or go to http://www.archives.gov/ federal register/code of federalregulations/ibr locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, Part, A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would amend Class D airspace and Class E airspace at Cape Cod Coast Guard Air Station, Falmouth, MA.

Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–