## § 95.2509

information contained in the database upon request:

- (2) Determine if an MBAN is within line-of-sight of an Aeronautical Mobile Telemetry (AMT) receive facility in the 2360-2390 MHz band and coordinate MBAN operations with the designated AMT frequency coordinator, as specified in §87.305 of this chapter;
- (3) Notify a registered health care facility when an MBAN has to change frequency within the 2360–2390 MHz band or to cease operating in the band, consistent with a coordination agreement between the MBAN and AMT frequency coordinators;
- (4) Develop procedures to ensure that registered health care facilities operate an MBAN consistent with the coordination requirements under this section; and
- (5) Identify the MBAN that is the source of interference in response to a complaint from the AMT coordinator and notify the health care facility of alternative frequencies available for MBAN use or to cease operation consistent with the rules.
- (c) Registration. Prior to operating MBAN devices that are capable of operation in the 2360–2390 MHz band, a health care facility must register with a frequency coordinator designated under §95.2509. Operation of MBAN devices in the 2360–2390 MHz band is prohibited prior to the MBAN coordinator notifying the health care facility that registration and coordination (to the extent coordination is required under paragraph (e) of this section) is complete. The registration must include the following information:
- (1) Specific frequencies or frequency range(s) within the 2360-2390 MHz band to be used, and the capabilities of the MBAN equipment to use the 2390-2400 MHz band;
- (2) Equivalent isotropically radiated power;
- (3) Number of MedRadio programmer/control transmitters in use at the health care facility as of the date of registration, including manufacturer name(s) and model number(s) and FCC identification number(s):
- (4) Legal name of the health care facility;
- (5) Location of MedRadio programmer/control transmitters (e.g., ge-

ographic coordinates, street address, building);

- (6) Point of contact for the health care facility (e.g., name, title, office address, phone number, fax number, email address); and,
- (7) In the event that an MBAN has to cease operating in all or a portion of the 2360-2390 MHz band due to interference under §95.2525 or changes in coordination under paragraph (e) of this section, a point of contact (including contractors) for the health care facility that is responsible for ensuring that this change is effected whenever it is required (e.g., name, title, office address, phone number, fax number, email address). The health care facility also must state whether, in such cases, its MBAN operation is capable of defaulting to the 2390-2400 MHz band and that it is responsible for ceasing MBAN operations in the 2360-2390 MHz band or defaulting traffic to other hospital systems.
- (d) Notification. A health care facility shall notify the MBAN frequency coordinator whenever an MBAN programmer/control transmitter in the 2360-2390 MHz band is permanently taken out of service, unless it is replaced with transmitter(s) using the same technical characteristics as those reported on the health care facility's registration, which will cover the replacement transmitter(s). A health care facility shall keep the information contained in each registration current and shall notify the MBAN frequency coordinator of any material change to the MBAN's location or operating parameters. In the event that the health care facility proposes to change the MBAN's location or operating parameters, the MBAN coordinator must first evaluate the proposed changes and comply with paragraph (e) of this section as appropriate before the health care facility may operate the MBAN in the 2360-2390 MHz band under changed operating parameters.
- (e) Coordination procedures. The MBAN coordinator will determine if an MBAN is within the line-of-sight of an AMT receive facility in the 2360-2390 MHz band and notify the health care facility when it may begin MBAN operations under the applicable procedures below.

- (1) If the MBAN is beyond the line-ofsight of an AMT receive facility, it may operate without prior coordination with the AMT coordinator, provided that the MBAN coordinator provides the AMT coordinator with the MBAN registration information and the AMT frequency coordinator concurs that the MBAN is beyond the lineof-sight prior to the MBAN beginning operations in the band.
- (2) If the MBAN is within line-ofsight of an AMT receive facility, the MBAN coordinator shall achieve a mutually satisfactory coordination agreement with the AMT coordinator prior to the MBAN beginning operations in the band. Such coordination agreement shall provide protection to AMT receive stations consistent with International Telecommunication (ITU) Recommendation ITU-R M.1459, "Protection criteria for telemetry systems in the aeronautical mobile service and mitigation techniques to facilitate sharing with geostationary broadcasting-satellite and mobile-satellite services in the bands 1 452-1525 and 2 310-2 360 MHz," May 2000, as adjusted using generally accepted engineering practices and standards that are mutually agreeable to both coordinators to take into account the local conditions and operating characteristics of the applicable AMT and MBAN facilities, and shall specify when the device shall limit its transmissions to segments of the 2360-2390 MHz band or must cease operation in the band. This ITU document is incorporated by reference into this section with the approval of the Director of the Federal Register under 5 U.S.C. 552(a) and 1 CFR part 5 1. To enforce any edition other than that specified in this section, the Federal Communications Commission must publish a document in the FEDERAL REGISTER and the material must be available to the public. Copies of the recommendation may be obtained from ITU, Place des Nations, 1211 Geneva 20, Switzerland, or online at http:// www.itu.int/en/publications/Pages/de-

fault.aspx. You may inspect a copy at the Federal Communications Commission, 445 12th Street SW., Washington, DC 20554, or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA call 202–741–6030 or go to http://www.archives.gov/federal\_register/

code of federal regulations/

- ibr\_locations.html. "Generally accepted engineering practices and standards" include, but are not limited to, engineering analyses and measurement data as well as limiting MBAN operations in the band by time or frequency.
- (3) If an AMT operator plans to operate a receive site not previously analyzed by the MBAN coordinator to determine line-of-sight to an MBAN facility, the AMT operator shall consider using locations that are beyond the line-of-sight of a registered health care facility. If the AMT operator determines that non-line-of-sight locations are not practical for its purposes, the AMT coordinator shall notify the MBAN coordinator upon no less than 7 days notice that the registered health care facility must cease MBAN operations in the 2360-2390 MHz band, unless the parties can achieve a mutually satisfactory coordination agreement under paragraph (e)(2) of this section.
- (f) Coordinator functions. The MBAN frequency coordinator shall:
- (1) Provide registration and coordination of MBAN operations to all eligible health care facilities on a non-discriminatory basis;
- (2) Provide MBAN registration and coordination services on a not-for-profit basis:
- (3) Notify the FCC of its intent to no longer serve as frequency coordinator at least six months prior to ceasing to perform these functions; and
- (4) Transfer the MBAN registration data in usable form to a frequency coordinator designated by the FCC if it ceases to be the coordinator.

## §§ 95.2511-95.2521 [Reserved]

## \$95.2523 MedRadio transmitter inspection.

Any non-implanted MedRadio transmitter must be made available for inspection upon request by an authorized FCC representative. Persons operating implanted or body-worn MedRadio