Wiping and Washing Systems, 105 Hydraulic Brake Systems, 106 Brake Hoses, 109 New Pneumatic Tires, 113 Hood Latch Systems, 116 Brake Fluid, 124 Accelerator Control Systems, 201 Occupant Protection in Interior Impact, 202 Head Restraints, 204 Steering Control Rearward Displacement, 205 Glazing Materials, 206 Door Locks and Door Retention Components, 207 Seating Systems, 209 Seat Belt Assemblies, 210 Seat Belt Assembly Anchorages, 212 Windshield Retention, 216 Roof Crush Resistance, 219 Windshield Zone Intrusion, and 302 Flammability of Interior Materials.

Additionally, the petitioner states that the non-U.S. certified 1995 Mercedes-Benz SL320 complies with the Bumper Standard found in 49 CFR Part 581 and with the Theft Prevention Standard found in 49 CFR Part 541.

Petitioner also contends that the vehicle is capable of being readily altered to meet the following standards, in the manner indicated:

Standard No. 101 *Controls and Displays:* (a) substitution of a lens marked "Brake" for a lens with a noncomplying symbol on the brake failure indicator lamp; (b) installation of a seat belt warning lamp that displays the appropriate symbol; (c) recalibration of the speedometer/odometer from kilometers to miles per hour.

Standard No. 108 Lamps, Reflective Devices and Associated Equipment: (a) installation of U.S.-model headlamp assemblies that incorporate headlamps with DOT markings; (b) installation of U.S.-model front and rear sidemarker/reflector assemblies; (c) installation of U.S.-model taillamp assemblies; (d) installation of a high-mounted stop lamp if the vehicle is not already so equipped.

Standard No. 110 *Tire Selection and Rims:* installation of a tire information placard.

Standard No. 111 Rearview Mirror: replacement of the passenger side rearview mirror with a U.S.-model component.

Standard No. 114 *Theft Protection*: installation of a warning buzzer microswitch in the steering lock assembly and a warning buzzer.

Standard No. 118 *Power Window Systems*: rewiring of the power window system so that the window transport is inoperative when the ignition is switched off.

Standard No. 208 Occupant Crash Protection: (a) installation of a U.S.-model seat belt in the driver's position, or a belt webbing-actuated microswitch inside the driver's seat belt retractor; (b) installation of an ignition switch-actuated seat belt warning lamp and

buzzer; (c) replacement of the driver's and passenger's side air bags and knee bolsters with U.S.-model components if the vehicle is not already so equipped. The petitioner states that the vehicle is equipped with combination lap and shoulder restraints that adjust by means of an automatic retractor and release by means of a single push button at both front designated seating positions, and with combination lap and shoulder restraints that release by means of a single push button at both rear outboard designated seating positions.

Standard No. 214 *Side Impact Protection*: installation of reinforcing beams.

Standard No. 301 *Fuel System Integrity*: installation of a rollover valve in the fuel tank vent line between the fuel tank and the evaporative emissions collection canister.

The petitioner also states that a vehicle identification number plate must be affixed to the vehicle to meet the requirements of 49 CFR Part 565.

Interested persons are invited to submit comments on the petition described above. Comments should refer to the docket number and be submitted to: Docket Section, National Highway Traffic Safety Administration, Room 5109, 400 Seventh Street, S.W., Washington, DC 20590. It is requested but not required that 10 copies be submitted.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above address both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the **Federal Register** pursuant to the authority indicated below.

**Authority:** 49 U.S.C. 30141(a)(1)(A) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: December 2, 1998.

## Marilynne Jacobs,

Director, Office of Vehicle Safety Compliance. [FR Doc. 98–32593 Filed 12–8–98; 8:45 am] BILLING CODE 4910–59–P

### **DEPARTMENT OF TRANSPORTATION**

National Highway Traffic Safety Administration

[Docket No. NHTSA-98-4800]

Notice of Receipt of Petition for Decision That Nonconforming 1984– 1992 BMW K100 Motorcycles Are Eligible for Importation

**AGENCY:** National Highway Traffic Safety Administration, DOT.

**ACTION:** Notice of receipt of petition for decision that nonconforming 1984–1992 BMW K100 motorcycles are eligible for importation.

**SUMMARY:** This document announces receipt by the National Highway Traffic Safety Administration (NHTSA) of a petition for a decision that 1984-1992 BMW K100 motorcycles that were not originally manufactured to comply with all applicable Federal motor vehicle safety standards are eligible for importation into the United States because (1) they are substantially similar to vehicles that were originally manufactured for importation into and sale in the United States and that were certified by their manufacturer as complying with the safety standards, and (2) they are capable of being readily altered to conform to the standards. **DATES:** The closing date for comments on the petition is January 8, 1999. **ADDRESSES:** Comments should refer to the docket number and notice number, and be submitted to: Docket Management, Room PL-401, 400 Seventh St., SW, Washington, DC 20590. [Docket hours are from 9 am to 5 pm]

FOR FURTHER INFORMATION CONTACT: George Entwistle, Office of Vehicle Safety Compliance, NHTSA (202–366– 5306)

# SUPPLEMENTARY INFORMATION:

### **Background**

Under 49 U.S.C. 30141(a)(1)(A), a motor vehicle that was not originally manufactured to conform to all applicable Federal motor vehicle safety standards shall be refused admission into the United States unless NHTSA has decided that the motor vehicle is substantially similar to a motor vehicle originally manufactured for importation into and sale in the United States, certified under 49 U.S.C. 30115, and of the same model year as the model of the motor vehicle to be compared, and is capable of being readily altered to conform to all applicable Federal motor vehicle safety standards.

Petitions for eligibility decisions may be submitted by either manufacturers or importers who have registered with NHTSA pursuant to 49 CFR Part 592. As specified in 49 CFR 593.7, NHTSA publishes notice in the **Federal Register** of each petition that it receives, and affords interested persons an opportunity to comment on the petition. At the close of the comment period, NHTSA decides, on the basis of the petition and any comments that it has received, whether the vehicle is eligible for importation. The agency then publishes this decision in the **Federal Register**.

Champagne Imports of Lansdale, Pennsylvania

("Champagne")(Registered Importer 90–009) has petitioned NHTSA to decide whether non-U.S. certified 1984–1992 BMW K100 motorcycles are eligible for importation into the United States. The vehicles which Champagne believes are substantially similar are 1984–1992 BMW K100 motorcycles that were manufactured for importation into, and sale in, the United States and certified by their manufacturer, Bayerische Motoren Werke, A.G., as conforming to all applicable Federal motor vehicle safety standards.

The petitioner claims that it carefully compared non-U.S. certified 1984–1992 BMW K100 motorcycles to their U.S. certified counterparts, and found the vehicles to be substantially similar with respect to compliance with most Federal motor vehicle safety standards.

Champagne submitted information with its petition intended to demonstrate that non-U.S. certified 1984–1992 BMW K100 motorcycles, as originally manufactured, conform to many Federal motor vehicle safety standards in the same manner as their U.S. certified counterparts, or are capable of being readily altered to conform to those standards.

Specifically, the petitioner claims that non-U.S. certified 1984–1992 BMW K100 motorcycles are identical to their U.S. certified counterparts with respect to compliance with Standard Nos. 106 Brake Hoses, 111 Rearview Mirrors, 116 Brake Fluid, 119 New Pneumatic Tires for Vehicles other than Passenger Cars, and 122 Motorcycle Brake Systems.

Petitioner additionally contends that the vehicles are capable of being readily altered to meet the following standard, in the manner indicated:

Standard No. 108 *Lamps, Reflective Devices and Associated Equipment:* Installation of U.S.-model head lamp assemblies.

Standard No. 120 *Tire Selection and Rims for Vehicles other than Passenger Cars:* Installation of a tire information label.

Standard No. 123 *Motorcycle Controls and Displays:* Installation of a U.S.-model speedometer/odometer calibrated in miles per hour.

The petitioner also states that a vehicle identification number plate will be affixed to the vehicle to meet the requirements of 49 CFR Part 565.

Comments should refer to the docket number and be submitted to: Docket Management, Room PL-401, 400 Seventh Street, S.W., Washington, DC 20590. It is requested but not required that 10 copies be submitted.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above address both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the **Federal Register** pursuant to the authority indicated below.

**Authority:** 49 U.S.C. 30141(a)(1)(A) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: December 2, 1998.

#### Marilynne Jacobs,

Director, Office of Vehicle Safety Compliance. [FR Doc. 98–32594 Filed 12–8–98; 8:45 am] BILLING CODE 4910–59–P

#### DEPARTMENT OF TRANSPORTATION

**Surface Transportation Board** 

[STB Docket No. AB-391 (Sub-No. 5X)]

Red River Valley & Western Railroad Company—Abandonment Exemption in Burleigh, Kidder and Stutsman Counties, ND

Red River Valley & Western Railroad Company (RRVW) has filed a notice of exemption under 49 CFR 1152 Subpart F—Exempt Abandonments to abandon approximately 59.70 miles of rail line from milepost 21.55, west of Woodworth, to milepost 81.25, in Regan, in Burleigh, Kidder and Stutsman Counties, ND. The line traverses United States Postal Service Zip Codes 58475, 58478, 58488, 58412, 58494 and 58477.

RRVW has certified that: (1) No local traffic has moved over the line for at least 2 years; (2) there is no overhead traffic moving over the line; (3) no formal complaint filed by a user of rail service on the line (or by a state or local government entity acting on behalf of such user) regarding cessation of service over the line either is pending with the Surface Transportation Board (Board) or

with any U.S. District Court or has been decided in favor of complainant within the 2-year period; and (4) the requirements at 49 CFR 1105.7 (environmental reports), 49 CFR 1105.8 (historic reports), 49 CFR 1105.11 (transmittal letter), 49 CFR 1105.12 (newspaper publication), and 49 CFR 1152.50(d)(1) (notice to governmental agencies) have been met.

As a condition to this exemption, any employee adversely affected by the abandonment shall be protected under Oregon Short Line R. Co.-Abandonment-Goshen, 360 I.C.C. 91 (1979). To address whether this condition adequately protects affected employees, a petition for partial revocation under 49 U.S.C. 10502(d) must be filed. Provided no formal expression of intent to file an offer of financial assistance (OFA) has been received, this exemption will be effective on January 8, 1999, unless stayed pending reconsideration. Petitions to stay that do not involve environmental issues,1 formal expressions of intent to file an OFA under 49 CFR 1152.27(c)(2),2 and trail use/rail banking requests under 49 CFR 1152.29 must be filed by December 21, 1998. Petitions to reopen or requests for public use conditions under 49 CFR 1152.28 must be filed by December 29, 1998, with: Surface Transportation Board, Office of the Secretary, Case Control Unit, 1925 K Street, N.W., Washington, DC 20423.

A copy of any petition filed with the Board should be sent to applicant's representative: Rose-Michele Weinryb, Esq., Weiner, Brodsky, Sidman & Kider, P.C., 1350 New York Avenue, N.W., Suite 800, Washington, DC 20005–4797.

If the verified notice contains false or misleading information, the exemption is void *ab initio*.

RRVW has filed an environmental report which addresses the abandonment's effects, if any, on the environment and historic resources. The Section of Environmental Analysis (SEA) will issue an environmental assessment (EA) by December 14, 1998. Interested persons may obtain a copy of the EA by writing to SEA (Room 500, Surface Transportation Board,

<sup>&</sup>lt;sup>1</sup>The Board will grant a stay if an informed decision on environmental issues (whether raised by a party or by the Board's Section of Environmental Analysis in its independent investigation) cannot be made before the exemption's effective date. See Exemption of Out-of-Service Rail Lines, 5 I.C.C.2d 377 (1989). Any request for a stay should be filed as soon as possible so that the Board may take appropriate action before the exemption's effective date.

<sup>&</sup>lt;sup>2</sup>Each offer of financial assistance must be accompanied by the filing fee, which currently is set at \$1000. *See* 49 CFR 1002.2(f)(25).