Corrections

Federal Register

Vol. 66, No. 38

Monday, February 26, 2001

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

DEPARTMENT OF ENERGY

Office of Energy Efficiency and Renewable Energy

10 CFR Part 430

[Docket Number EE-RM-98-440]

RIN 1904-AA77

Energy Conservation Program for Consumer Products; Central Air Conditioners and Heat Pumps Energy Conservation Standards

Correction

In rule document 01–1790 beginning on page 7170, in the issue of Monday, January 22, 2001, make the following corrections:

- 1. On page 7187, in table V.11., under the heading "ARI manufacturing costs (in percent), in the third line, "0.2" should read "10.2".
- 2. On page 7190, in table V.18., in the second level heading, "unites" should read "units".
- 3. On the same page, in the same table, under the heading "Reverse engineering costs", the heading "Rool–up" should read "Roll–up".

 4. On page 7191, in table V.19., in the
- 4. On page 7191, in table V.19., in the last column on the right, under the heading "as percent of base case total". the following numbers; "0.2, 0.5, and 0.9" should read "-0.2, -0.5, -0.9"

[FR Doc. C1–1790 Filed 2–23–01; 8:45 am] BILLING CODE 1505–01–D