and placed in the Rules Docket (otherwise, an evaluation is not required). A copy of it, if filed, may be obtained from the Rules Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by Reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. FAA amends § 39.13 by adding a new airworthiness directive (AD) to read as follows:

2003–10–05 Raytheon Aircraft Company: Amendment 39–13150; Docket No. 2003–CE–17–AD.

(a) What airplanes are affected by this AD? This AD applies to Model 390 airplanes,

serial numbers RB–18 through RB–24, that are certificated in any category.

(b) Who must comply with this AD? Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) What problem does this AD address? The actions specified by this AD are intended to require the use of necessary flight information to prevent runway overruns based on insufficient wheel braking if the lift dump spoilers do not operate after landing touchdown. This could result in reduced or loss of control of the airplane.

(d) What must I do to address this problem? To address this problem, you must accomplish the following actions:

| Actions | Compliance | | |
|--|---|--|--|
| (1) Incorporate information into the FAA-approved Airplane Flight Manual (AFM) that would add requirements for "Landing Performance for Operation of the Airplane with Lift Dump Inoperative." Accomplish this action by inserting Raytheon Temporary Change to the FAA Approved Airplane Flight Manual P/N 390–590001–0003BTC5A1, revised March 24, 2003. | Within the next 5 hours time-in-service (TIS) after May 30, 2003 (the effective date of this AD). | | |
| (2) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may incorporate into the AFM the information specified in paragraph (d)(1) of this AD. Make an entry into the aircraft records showing compliance with this portion of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9). | Within the next 5 hours TIS after May 30, 2003 (the effective date of this AD). | | |

- (e) Are special flight permits authorized for this AD? Special flight permits are not authorized for this AD. On July 10, 2002, FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system. Part of this amendment to 14 CFR part 39 authorized special flight permits for all ADs, unless specified otherwise. Because the owner/operator holding an appropriate pilot's license may accomplish the action of this AD and the compliance time is 5 hours TIS after the AD effective date, FAA has determined that special flight permits are not necessary for this AD.
- (f) Can I comply with this AD in any other way? To use an alternative method of compliance or adjust the compliance time, follow the procedures in 14 CFR 39.19. Send these requests to the Manager, Wichita Aircraft Certification Office (ACO). For information on any already approved alternative methods of compliance, contact Derek Morgan, Flight Test Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946–4172; facsimile: (316) 946–4107.
- (g) Are any service bulletins incorporated into this AD by reference? Actions required by this AD must be done in accordance with Raytheon Temporary Change to the FAA Approved Airplane Flight Manual P/N 390–590001–0003BTC5A1, revised March 24, 2003. The Director of the Federal Register previously approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51 as of April 7, 2003 (68 FR 16205, April 3, 2003). You can get copies from Raytheon Aircraft Company, 9709 E. Central,

Wichita, Kansas 67201–0085; telephone: (800) 429–5372 or (316) 676–3140. You may view this information at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) When does this amendment become effective? This amendment becomes effective on May 30, 2003.

Issued in Kansas City, Missouri, on May 12, 2003.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–12240 Filed 5–15–03; 8:45 am] $\tt BILLING$ CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30368; Amdt. No. 3058]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard

Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These change are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective May 16, 2003. the compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 16,

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination—

- 1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
- 2. The FAA Regional Office of the region in which affected airport is located; or
- 3. The Flight Inspection Area Office which originated the SIAP.

4. The Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC

For Purchase—Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional office of the region in which the affected airport is located.

By Subscription—Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS–420), Flight technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) telephone: (405) 965–4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description on each SIAP is contained in the appropriate FAA Form 8260 and the National Flight Data Center (FDC)/Permanent (P) Notices to Airmen (NOTAM) which are incorporated by reference in the amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation's Regulations (FAR). Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the Federal Register expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction of charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form

documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

The Rule

This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes SIAPs. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained in the content of the following FDC/P NOTAMs for each SIAP. The SIAP information in some previously designated FDC/Temporary (FDC/T) NOTAMs is of such duration as to be permanent. When conversion to FDC/P NOTAMs, the respective FDC/T NOTAMs have been canceled.

The FDC/P NOTAMs for the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these chart changes to SIAPs by FED/P NOTAMs, the TERPS criteria were applied to only these specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a National Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for all these SIAP amendments requires making them effective in less than 30 days.

Further, the SIAPs contained in this amendment are based on the criteria contained in the TERPs. Because of the close and immediate relationship between these SIAPs and safety in air commerce. I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making these SIAPs effective in less than 30 days.

Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which

frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 97

Air traffic control, Airports, Incorporation by reference, and Navigation (air).

Issued in Washington, DC on May 9, 2003. **James J. Ballough**,

Director, Flight Standards Service.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me, part 97 of the Federal Aviation Regulations (14 CFR part 97) is amended by establishing, amending, suspending, or revoking Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

■ 2. Part 97 is amended to read as follows:

$\S 97.23,\,97.25,\,97.27,\,97.29,\,97.31,\,97.33,\,$ and 97.35.

By amending: § 97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC LOC/DME, LDA, LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, ISMLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAV SIAPs; and § 97.35 COPTER SIAPs, Identified as follows:

* * * Effective Upon Publication

| FDC date | State | City | Airport | FDC No. | Subject |
|----------|-------|---------------|----------------------------|---------|--------------------------|
| 04/21/03 | LA | MONROE | MONROE REGIONAL | 3/3081 | VOR/DME RWY 4, AMDT 1 |
| 04/21/03 | LA | MONROE | MONROE REGIONAL | 3/3082 | VOR RWY 4, AMDT 17A |
| 04/21/03 | TX | WICHITA FALLS | SHEPPARD AFB/WICHITA FALLS | 3/3091 | RNAV (GPS) RWY 33L, ORIG |
| | | | MUNI. | | |
| 04/25/03 | AZ | SAFFORD | SAFFORD REGIONAL | 3/3202 | GPS RWY 12, ORIG |
| 04/25/03 | AZ | SAFFORD | SAFFORD REGIONAL | 3/3203 | GPS RWY 30, ORIG |

| FDC date | State | City | Airport | | FDC No. | Subject |
|----------|-------|---------------|------------------------------|--------------|---------|-----------------------------|
| 04/29/03 | AR | MOUNTAIN VIEW | MOUNTAIN VIEW RIAL FIELD. | WILCOX MEMO- | 3/3278 | NDB-A, AMDT 2A |
| 04/30/03 | KY | LONDON | LONDON-CORBIN FIELD. | ARPT-MAGEE | 3/3120 | GPS RWY 5, ORIG-A |
| 04/30/03 | KY | LONDON | LONDON-CORBIN FIELD. | ARPT-MAGEE | 3/3121 | GPS RWY 23, ORIG-A |
| 04/30/03 | KY | LONDON | LONDON-CORBIN FIELD. | ARPT-MAGEE | 3/3122 | VOR RWY 5, AMDT 12C |
| 04/30/03 | KY | LONDON | LONDON-CORBIN FIELD. | ARPT-MAGEE | 3/3123 | VOR/DME RNAV RWY 5, AMDT 3C |
| 04/30/03 | AZ | PHOENIX | PHOENIX SKY HARBOR INTL | | 3/3313 | RNAV (GPS) RWY 25R, ORIG |
| 04/30/03 | AZ | PHOENIX | PHOENIX SKY HARBOR INTL | | 3/3314 | RNAV (GPS) RWY 25L, ORIG |
| 04/30/03 | AZ | PHOENIX | PHOENIX SKY HARBOR INTL | | 3/3315 | ILS RWY 25L, AMDT 1A |
| 05/06/03 | NY | ALBANY | ALBANY INTL | | 3/3407 | ILS RWY 19, AMDT 21B |
| 05/06/03 | TX | CLEVELAND | CLEVELAND MUNI | | 3/3448 | VOR-A, AMDT 4A |

[FR Doc. 03–12174 Filed 5–15–03; 8:45 am] BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30367; Amdt. No. 3057]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective May 16, 2003. The compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 16, 2003

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

- 2. The FAA Regional Office of the region in which the affected airport is located;
- 3. The Flight Inspection Area Office which originated the SIAP; or,
- 4. The Office of Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

For Purchase—Individual SIAP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription—Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT:

Donald P. Pate, Flight Procedure Standards Branch (AMCAFS–420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) telephone: (405) 954–4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260–3, 8260–4, and 8260–5. Materials incorporated

by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the Federal Register expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unneccesary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

The Rule

This amendment to part 97 is effective upon publication of each separate SIAP as contained in the transmittal. Some SIAP amendments may have been previously issued by the FAA in a National Flight Data Center (NFDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP amendments may require making them effective in less than 30 days. For the remaining SIAPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between