### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

# § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

#### BAE Systems (Operations) Limited (Formerly British Aerospace Regional Aircraft): Docket 2001–NM–288–AD.

Applicability: All Model Jetstream 4101 airplanes, certificated in any category. Compliance: Required as indicated, unless

accomplished previously.

To prevent failure of the steering pinion in the nose landing gear (NLG), which could result in a loss of steering and possible damage to the airplane during takeoff and landing, accomplish the following:

#### Identification of Steering Pinion Part Number and Follow-on/Corrective Actions

(a) Within 60 days after the effective date of this AD: Do a review of the airplane maintenance records and a general visual inspection of the NLG to identify the part number (P/N) of the steering pinion, and to determine the total cycles since new and since overhaul of the NLG, by accomplishing all of the applicable actions in accordance with Part 1 of the Accomplishment Instructions of BAE Systems (Operations) Limited Service Bulletin J41–32–076, dated July 3, 2001.

Note 1: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(b) If the steering pinion P/N is identified as AIR136088, and the NLG has more than 12,000 total landings since new or overhaul: Before further flight, after accomplishing the actions required by paragraph (a) of this AD, install a temporary placard prohibiting pushback with engines running in accordance with Part 1 of the Accomplishment Instructions of BAE Systems (Operations) Limited Service Bulletin J41–32–076, dated July 3, 2001.

(c) Based on the criteria in the Accomplishment Instructions of BAE Systems (Operations) Limited Service Bulletin J41–32–076, dated July 3, 2001, if it is determined that the NLG must be replaced with a serviceable NLG, accomplish the replacement in accordance with the Accomplishment Instructions of the service bulletin. Do the replacement at the later of the times specified in paragraphs (c)(i) and (c)(ii) of this AD. After replacement of an existing NLG the temporary placard required by paragraph (b) of this AD may be removed from the airplane.

- (i) Prior to the accumulation of 12,000 total landings on the NLG since new or overhaul.
- (ii) Within 1,000 landings or 16 months after the effective date of this AD, whichever occurs first.

## Repetitive Replacement

(d) After the initial replacement of a NLG as required by paragraph (c) of this AD: Replace the NLG with a serviceable NLG thereafter at intervals not to exceed 12,000 landings on the NLG, until accomplishment of paragraph (f) of this AD.

(e) If P/N AIR131714 is installed on the airplane, or if an operator installs this P/N as a serviceable replacement part, this part must be replaced at or before the accumulation of 19,000 total landings on the part, and thereafter at intervals not to exceed 19,000 total landings on the part, until accomplishment of paragraph (f) of this AD.

(f) Replacement of a NLG with a new NLG having P/N AIR83586–18, or any P/N AIR83586–xx (where xx represents the "dash" number of the part) with "mod 19 strike-off" recorded on the nameplate, in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Service Bulletin J41–32–077, dated August 31, 2001, restores the life limits of the steering pinion to 60,000 landings on the NLG. Replace the NLG thereafter at intervals not to exceed 60,000 landings on the NLG.

# Submission of Information to Manufacturer Not Required

(g) Although the service bulletins referenced in this AD specify to notify the manufacturer when the actions in the service bulletins have been accomplished, this AD does not include such a requirement.

### **Alternative Methods of Compliance**

(h) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, is authorized to approve alternative methods of compliance for this AD.

**Note 2:** The subject of this AD is addressed in British airworthiness directive 001–07–2001.

Issued in Renton, Washington, on February 17, 2004.

#### Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 04–4048 Filed 2–24–04; 8:45 am] BILLING CODE 4910–13–P

### **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No. FAA-2003-16705; Airspace Docket No. 03-AGL-20]

## Proposed Modification of Class D Airspace; Mount Clemens, MI

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This document proposes to modify Class D airspace at Mount Clemens, MI. Instrument Flight Rules (IFR) Category E circling procedures are being used at Selfridge Air National Guard Base, MI. Increasing the current radius of the Class D airspace area will allow for a lower Circling Minimum Descent Altitude. Controlled airspace extending upward from the surface of the earth is needed to contain aircraft executing these approach procedures. This action would increase the area of the existing controlled airspace for Selfridge Air National Guard Base, Mount Clemens, MI.

**DATES:** Comments must be received on or before April 10, 2004.

ADDRESSES: Send comments on the proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket Number FAA-2003-16705/ Airspace Docket No. 03-AGL-20, at the beginning of your comments. You may also submit comments on the internet at http://dms.dot.gov. You may review the public docket containing the proposal, and comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

# FOR FURTHER INFORMATION CONTACT:

Patricia A. Graham, Air Traffic Division, Airspace Branch, AGL–520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294–7568.

## SUPPLEMENTARY INFORMATION:

#### Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this document must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2003-16705/Airspace Docket No. 03-AGL-20." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket, FAA, Great Lakes Region, Office of the Regional Counsel, 2300 East Devon Avenue, Des Plaines, Illinois, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

# Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at http://dms.dot.gov. Recently published rulemaking documents can also be accessed through the FAA's web page at http://www.faa.gov or the Superintendent of Documents web page at http://www.access.gpo.gov/nara.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, Office of Air Traffic Airspace Management, ATA–400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267–8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267–9677, to request a copy of Advisory Circular

No. 11–2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

## The Proposal

The FAA is considering an amendment to 14 CFR part 71 to modify Class D airspace at Mount Clemens, MI, for Selfridge ANGB. Controlled airspace extending upward from the surface of the earth is needed to contain aircraft executing instrument approach procedures. The area would be depicted on appropriate aeronautical charts. Class D airspace areas extending upward from the surface of the earth are published in paragraph 5000 of FAA Order 7400.9L dated September 2, 2003, and effective September 16, 2003, which is incorporated by reference in 14 CFR 71.1. The Class E designations listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an establishment body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore this, proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

## The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

# PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR 1959–1963 Comp., p. 389.

#### §71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9L, Airspace Designations and Reporting Points, dated September 2, 2003, and effective September 16, 2003, is amended as follows:

D leans of D :

Paragraph 5000 Class D airspace.

#### AGL MI D Mount Clemens, MI [Revised]

Mount Clemens, Selfridge Air National Guard Base, MI

(Lat. 42°36′03″N., long. 82°50′14″.)

That airspace extending upward from the surface to and including 3,100 feet MSL within a 6.6-mile radius of the Selfridge Air National Guard Base. This Class D airspace is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

Issued in Des Plaines, Illinois on January 29, 2004.

#### Nancy B. Shelton,

Manager, Air Traffic Division, Great Lakes Region.

[FR Doc. 04–4183 Filed 2–24–04; 8:45 am] BILLING CODE 4910–13–M

#### **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

### 14 CFR Part 71

[Docket No. FAA-2003-16693; Airspace Docket No. 03-AGL-21]

Proposed Establishment of Class D Airspace; St. Cloud, MN; Proposed Modification of Class E Airspace; St. Cloud, MN

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This document proposes to establish Class D airspace at St. Cloud, MN, and modify Class E airspace at St. Cloud, MN. Standard Instrument Approach Procedures (SIAPS) to several runways have been developed for the St. Cloud Regional Airport. Controlled airspace extending upward from the surface of the earth is needed to contain aircraft executing these approaches. Additionally, an Air Traffic Control Tower is under construction. This action would establish a radius of Class D airspace, and increase the existing area of Class E airspace for St. Cloud Regional Airport.

**DATES:** Comments must be received on or before April 10, 2004.