

(1) Within 5,000 flight cycles after the last inspection required by paragraph (g)(1) or (g)(2) of this AD as applicable.

(2) Within 6 months after the effective date of this AD.

(i) If any cracking is found during any inspection required by this AD, before further flight, accomplish all applicable corrective actions, in accordance with the Accomplishment Instructions and figures of Airbus Mandatory Service Bulletin A320-27A1186, Revision 07, dated March 2, 2011.

**Parts Installation**

(j) As of the effective date of this AD, no person may install on any airplane an elevator servo-control rod eye-end unless it is new or has been inspected in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A320-27A1186, Revision 07, dated March 2, 2011, with no crack findings.

**Credit for Actions Accomplished in Accordance With Previous Service Information**

(k) Actions done before the effective date of this AD in accordance with the service information specified in table 1 of this AD are acceptable for compliance with the corresponding requirements of paragraphs (g)(1) and (g)(2) of this AD. Actions done before the effective date of this AD in accordance with the service information specified in table 2 of this AD are acceptable for compliance with the corresponding requirements of paragraph (h) of this AD.

**TABLE 1—CREDIT SERVICE INFORMATION FOR PARAGRAPH (G) OF THIS AD**

Airbus AOT—	Revision—	Dated—
A320-27A1186 .....	Original .....	June 23, 2008.
A320-27A1186 .....	01 .....	August 11, 2008.
A320-27A1186 .....	02 .....	March 30, 2009.
A320-27A1186 .....	03 .....	April 1, 2009.
A320-27A1186 .....	04 .....	April 3, 2009.

**TABLE 2—CREDIT SERVICE INFORMATION FOR PARAGRAPH (H) OF THIS AD**

Airbus Service Bulletin—	Revision—	Dated—
A320-27A1186 .....	05 .....	March 10, 2010.
A320-27A1186 .....	06 .....	December 14, 2010.

**FAA AD Differences**

**Note 1:** This AD differs from the MCAI and/or service information as follows: No differences.

**Other FAA AD Provisions**

(l) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to *Attn: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1405; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.* Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD. AMOCs approved previously in accordance with AD 2009-17-04, Amendment 39-15995 (74 FR 41611, August 18, 2009), are approved as AMOCs for the corresponding provisions of this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-

approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

**Related Information**

(m) Refer to MCAI EASA Airworthiness Directive 2010-0046, dated March 19, 2010; and Airbus Mandatory Service Bulletin A320-27A1186, Revision 07, dated March 2, 2011; for related information.

**Material Incorporated by Reference**

(n) You must use Airbus Mandatory Service Bulletin A320-27A1186, Revision 07, including Appendices 1, 2, 3, 4, 5, and 6, dated March 2, 2011, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office—EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: *account.airworth-eas@airbus.com*; Internet *http://www.airbus.com*.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go

to: *http://www.archives.gov/federal\_register/code\_of\_federal\_regulations/ibr\_locations.html*.

Issued in Renton, Washington, on September 7, 2011.

**Jeffrey E. Duven,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2011-23468 Filed 9-15-11; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

[Docket No. FAA-2011-0515; Airspace Docket No. 11-ANM-11]

**Amendment of Class E Airspace; Miles City, MT**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies Class E airspace at Miles City, MT, to accommodate aircraft using a new Area Navigation (RNAV) Global Positioning System (GPS) standard instrument approach procedures at Frank Wiley Field. Additionally, the geographic coordinates for Frank Wiley Field are being adjusted. This improves the safety

and management of Instrument Flight Rules (IFR) operations at the airport.

**DATES:** Effective date, 0901 UTC, December 15, 2011. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:** Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue, SW., Renton, WA 98057; telephone (425) 203-4537.

**SUPPLEMENTARY INFORMATION:**

**History**

On July 15, 2011, the FAA published in the **Federal Register** a notice of proposed rulemaking to modify controlled airspace at Miles City, MT (76 FR 41725). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6002 and 6005, respectively, of FAA Order 7400.9V dated August 9, 2011, and effective September 15, 2011, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in that Order.

**The Rule**

This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 by modifying Class E surface airspace, and Class E airspace extending upward from 700 feet above the surface, at Frank Wiley Field, Miles City, MT, to accommodate IFR aircraft executing new RNAV (GPS) standard instrument approach procedures at the airport. This action also adjusts the geographic coordinates for Frank Wiley Field to coincide with the FAA's aeronautical database. This action is necessary for the safety and management of IFR operations.

The FAA has determined this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air

traffic procedures and air navigation, it is certified this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106 discusses the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies controlled airspace at Frank Wiley Field, Miles City, MT.

**List of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

**Adoption of the Amendment**

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

**PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E. O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

**§ 71.1 [Amended]**

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9V, Airspace Designations and Reporting Points, dated August 9, 2011, and effective September 15, 2011 is amended as follows:

*Paragraph 6002 Class E airspace designated as surface areas.*

\* \* \* \* \*

**ANM MT E2 Miles City, MT [Modified]**

Miles City, Frank Wiley Field, MT  
(Lat. 46°25'41" N., long. 105°53'11" W.)

Within a 4.9-mile radius of Frank Wiley Field, and within 3 miles each side of the 226° bearing of Frank Wiley Field extending from the 4.9-mile radius to 10.8 miles southwest of the airport, and within 3 miles each side of the 253° bearing of Frank Wiley Field extending from the 4.9-mile radius to 9.4 miles west of the airport. This Class E airspace area is effective during the specific dates and times established in advance by a

Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

*Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.*

\* \* \* \* \*

**ANM MT E5 Miles City, MT [Modified]**

Miles City, Frank Wiley Field, MT  
(Lat. 46°25'41" N., long. 105°53'11" W.)

That airspace extending upward from 700 feet above the surface within a 7.4-mile radius of Frank Wiley Field, and within 3.1 miles each side of the 047° bearing from Frank Wiley Field extending from the 7.4-mile radius to 15.5 miles northeast of the airport, and within 3.5 miles each side of the 226° bearing from Frank Wiley Field, extending from the 7.4-mile radius to 15 miles southwest of the airport, and within 4.5 miles each side of the 253° bearing from Frank Wiley Field, extending from the 7.4-mile radius to 12 miles west of the airport; that airspace extending upward from 1,200 feet above the surface within a 34.5-mile radius of Frank Wiley Field.

Issued in Seattle, Washington, on September 7, 2011.

**John Warner,**

*Manager, Operations Support Group, Western Service Center.*

[FR Doc. 2011-23693 Filed 9-15-11; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

[Docket No. FAA-2011-0517; Airspace Docket No. 11-AWP-7]

**Establishment of Class E Airspace; Chinle, AZ**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action establishes Class E airspace at Chinle Municipal Airport, Chinle, AZ, to accommodate aircraft using a new Area Navigation (RNAV) Global Positioning System (GPS) standard instrument approach procedures at Chinle Municipal Airport. This improves the safety and management of Instrument Flight Rules (IFR) operations at the airport.

**DATES:** Effective date, 0901 UTC, December 15, 2011. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:** Eldon Taylor, Federal Aviation