

Office, as appropriate. If sending information directly to the Airframe and Mechanical Systems Branch, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2015-28, dated October 21, 2015, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-5819.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 601R-25-201, dated July 21, 2015.

(ii) Bombardier Service Bulletin 670BA-25-100, dated July 21, 2015.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 19, 2015.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-30182 Filed 11-27-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2015-4514; Airspace Docket No. 15-AEA-9]

Amendment of Class E Airspace for the Following New York Towns: Elmira, NY; Ithaca, NY; Poughkeepsie, NY

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; technical amendment.

SUMMARY: This action amends Class E Airspace at Elmira/Corning Regional Airport, Elmira, NY; Ithaca Tompkins Regional Airport, Ithaca, NY; and Dutchess County Airport, Poughkeepsie, NY, by eliminating the Notice to Airmen (NOTAM) part time status of the Class E surface airspace designated as an extension at each airport. This action also updates the geographic coordinates of each airport to coincide with the FAA's database, and recognizes the airport name for Ithaca Tompkins Regional Airport. This is an administrative change to coincide with the FAA's aeronautical database.

DATES: Effective 0901 UTC, February 4, 2016. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at <http://www.faa.gov/airtraffic/publications/>. For further information, you can contact the Airspace Policy and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202-267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/code-of-federal-regulations/ibr-locations.html>.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part, A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends Class E airspace at the New York airports listed in this final rule.

History

In a review of the airspace, the FAA found the airspace description for Elmira/Corning Regional Airport, Elmira, NY; Ithaca Tompkins Regional Airport, Ithaca, NY; and Dutchess County Airport, Poughkeepsie, NY, as published in FAA Order 7400.9Z, Airspace Designations and Reporting Points, does not match the FAA's charting information. This administrative change coincides with the FAA's aeronautical database for Class E Airspace Designated as an Extension to a Class D Surface Area.

Class E airspace designations are published in paragraphs 6004 of FAA Order 7400.9Z dated August 6, 2015, and effective September 15, 2015, which is incorporated by reference in 14 CFR part 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the **ADDRESSES** section of this final rule. FAA Order 7400.9Z lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by eliminating the NOTAM information that reads "This Class E airspace area is effective during the specific dates and time established in advance by Notice to

Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.” from the regulatory text of the Class E airspace designated as an extension to Class D at Elmira/Corning Regional Airport, Elmira, NY; Ithaca Tompkins Regional Airport, Ithaca, NY; and Dutchess County Airport, Poughkeepsie, NY. Additionally, the geographic coordinates for each airport are updated to be in concert with the FAA’s aeronautical database. Also the FAA recognizes the airport’s name change from Tompkins County Airport, Ithaca, NY, to Ithaca Tompkins Regional Airport, Ithaca, NY.

This is an administrative change amending the description for the above New York airports, to be in concert with the FAA’s aeronautical database, and does not affect the boundaries, or operating requirements of the airspace, therefore, notice and public procedure under 5 U.S.C. 553(b) are unnecessary.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, “Environmental Impacts: Policies and Procedures,” paragraph 311a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR Part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120, E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, effective September 15, 2015, is amended as follows:

Paragraph 6004 Class E Airspace Designated as an Extension to a Class D Surface Area

* * * * *

AEA NY E4 Elmira, NY [Amended]

Elmira/Corning Regional Airport, Elmira, NY
(Lat. 42°09′35″ N., long. 76°53′30″ W.)

Elmira VOR/DME

(Lat. 42°05′40″ N., long. 77°01′29″)

ERINN OM

(Lat. 42°12′18″ N., long. 76°49′09″ W.)

That airspace extending upward from the surface within 1.8 miles each side of the Elmira VOR/DME 057° radial extending from the 4.2-mile radius to the VOR/DME and within 1.8 miles each side of the Elmira/Corning Regional Airport ILS localizer northeast course extending from the 4.2-mile radius to 1.8 miles northeast of the ERINN OM and within 1.8 miles each side of the centerline of Runway 10 extended easterly from the 4.2-mile radius of the airport for 1.1 miles and within 1.8 miles each side of the centerline of Runway 28 extended westerly from the 4.2-mile radius for 3.7 miles.

* * * * *

AEA NY E4 Ithaca, NY [Amended]

Ithaca Tompkins Regional Airport, Ithaca, NY

(Lat. 42°29′29″ N., long. 76°27′31″ W.)

Ithaca VOR/DME

(Lat. 42°29′42″ N., long. 76°27′35″ W.)

That airspace extending upward from the surface from the 4-mile radius of the Tompkins Regional Airport to the 5.7-mile radius of the Tompkins Regional Airport clockwise from the 329° bearing to the 081° bearing from the airport, that airspace from the 4-mile radius of Tompkins County Airport to the 8.7-mile radius of the Tompkins Regional Airport extending clockwise from the 081° bearing to the 137° from the airport, that airspace from the 4-mile radius of Tompkins Regional Airport to the 6.6-mile radius of the Tompkins Regional Airport extending clockwise from the 137° bearing to the 170° bearing from the airport,

that airspace from the 4-mile radius to the 5.7-mile radius of the Tompkins Regional Airport extending clockwise from the 170° bearing to the 196° bearing from the airport and that airspace within 2.7 miles each side of the Ithaca VOR/DME 305° radial extending from the 4-mile radius of Tompkins Regional Airport to 7.4 miles northwest of the Ithaca VOR/DME.

* * * * *

AEA NY E4 Poughkeepsie, NY [Amended]

Dutchess County Airport, Poughkeepsie, NY
(Lat. 41°37′36″ N., long. 73°53′03″ W.)

Kingston VORTAC

(Lat. 41°39′55″ N., long. 73°49′20″ W.)

That airspace extending upward from the surface within 3.1 miles each side of the Kingston VORTAC 025° radial extending from the VORTAC to 8.3 miles northeast of the VORTAC and within 1.8 miles each side of the Kingston VORTAC 231° radial extending from the 4-mile radius to 9.2 miles southwest of the VORTAC and within 3.1 miles each side of the Kingston VORTAC 050° radial extending from the VORTAC to 9.2 miles northeast of the VORTAC.

Issued in College Park, Georgia, on November 17, 2015.

Ryan W. Almasy,

Acting Manager, Operations Support Group,
Eastern Service Center, Air Traffic
Organization.

[FR Doc. 2015–30187 Filed 11–27–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[TD 9741]

RIN 1545–BB23; 1545–BC07; 1545–BH48

General Allocation and Accounting Regulations Under Section 141; Remedial Actions for Tax-Exempt Bonds; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Final regulations; correcting amendment.

SUMMARY: This document contains corrections to final regulations (TD 9741) that were published in the **Federal Register** on Tuesday, October 27, 2015 (80 FR 65637). The final regulations provide guidance on allocation and accounting, and certain remedial actions, for purposes of the private activity bond restrictions under section 141 of the Internal Revenue Code that apply to tax-exempt bonds issued by State and local governments.

DATES: This correction is effective November 30, 2015 and applicable October 27, 2015.