


JSD-100 USB Driver Debugging Tips

The first versions of the GUI prior to version 1.8.8 used a driver package that is not certified and will not work with the current versions of the JSD-100 application. One method to verify this is the name of the USB device driver as shown below “LibUsbDevices.” This driver will require removal and the **Check Box** for delete must be set.



After removing the driver, the USB plug must be disconnected. It is **Important To, Wait** when reconnecting the USB cable to allow the OS to recognize the device as Unknown or Other with the name “USL JSD-100 Cinema Processor.” Select the USL device and update the driver. The driver is available in the “C:\Program Files (x86)\USL\JSD-100\WinUSB_Drivers” folder.

JSD-100 USB Driver Debugging Tips

When the correct driver is installed, the device manager shows it as “libusb (WinUSB) devices.” Note the difference in the name, as it is an indication of the installation status.

